

Prepared for: City of Racine 730 Washington Avenue Racine, WI 53403 Prepared by: AECOM 1555 N RiverCenter Dr. Suite 214 Milwaukee, WI 53212 60263726 December 2013

Root River Streambank Erosion and Outfall Assessment Final Report



Contents

1.0	Sumn	nary		
	1.1	Backgr	round	1-1
	1.2	Data C	Collection	1-1
	1.3	Data A	nalysis Methodology and Findings	1-2
	1.4	Recom	nmendations	1-3
2.0	Introd	luction.		
	2.1	Backgr	round	2-1
	2.2	Goals a	and Objectives	2-2
3.0	Previo	ous and	I Ongoing Studies and Projects	
		3.1.1	WDNR Stream Classification	3-1
		3.1.2	City of Racine Streambank Stabilization Projects	3-1
		3.1.3		
4.0	Data (Collectio	on	4-1
	4.1	Stream	hbank Data and Analysis Methodology	4-1
	4.2	Outfall	Data	4-2
5.0	Data /	Analysis	S	5-1
	5.1	Stream	nbank Erosion Analysis	5-1
		5.1.1	BEHI Analysis	5-1
		5.1.2	Pfankuch Rating	5-1
		5.1.3	Visual Observations	5-2
	5.0	5.1.4		
	5.2	Erosion	n Raung	5-2
	5.3	Outrall	Assessment	5-2
	5.4	Photo I		5-3
	5.5	Compa	arison to the 2004-2005 Assessment	5-3
6.0	Concl	lusions	and Recommendations	6-1
	6.1	High R	ated Erosion Areas	6-1
	6.2	Stabiliz	zation Methods	6-3
		6.2.1	Instream Practices	6-3
		6.2.2	Streambank Treatment	6-4

	6.3	Recommended Treatments	.6-7
	6.4	Special Features	.6-7
	6.5	Outfall Replacements	.6-7
	6.6	Maintenance	.6-8
	6.7	Permitting	.6-9
7.0	Projec	t Implementation	7-1
	7.1	Cost Estimating Methods	.7-1
	7.2	Priority Stream Segment Costs	.7-1
	7.3	Outfall Replacement Costs	.7-1
	7.4	Funding Opportunities	.7-1
8.0	Refere	nces	8-1

List of Tables

- Table 3-1 Historical Design/Construction Projects
- Table 5-1 Bank Erodibility Hazard Index
- Table 5-2 Pfankuch Channel Stability Rating
- Table 5-3 Visual Rating
- Table 5-4 Adjacent Land Use
- Table 5-5 Weighting of Ratings
- Table 5-6 Overall Erosion Ratings
- Table 5-7 Outfall Assessments
- Table 6-1 Alternative Stabilization Practices
- Table 6-2 Streambank Buffer Seed Mixture
- Table 7-1 Cost for Stream Stabilization Practices
- Table 7-2 to 7-12 Estimated Streambank Stabilization Costs
- Table 7-13 Outfall Replacement Cost Estimates
- Table 7-14 Streambank Funding Opportunities

List of Figures

- 1-1 Root River within City Limits
- 1-2 Root River within City Limits
- 5-1 to 5-5 Root River Erosion Areas
- 5-6 to 5-25 Root River Photo Location Areas Root River Assessment
- 5-26 to 5-30 Bank Erosion Comparison Root River Assessment

List of Appendices

Appendix A BEHI Worksheet and Rating Guide

- Appendix B Pfankuch Rating Worksheet
- Appendix C Photo Logs

1.0 Summary

This study was conducted to evaluate the condition of the streambanks and storm sewer outfalls along the Root River within the limits of the City of Racine (the City) and the associated erosion and erosion potential. This report represents a compilation of this study. It includes a discussion on the field methods and activities and presents Geographic Information Systems (GIS) maps of the streambank and outfall assessment results. Potential mitigation measures for critical areas in addition to associated permitting requirements, and potential grant funding sources have also been included.

The project goal was to develop an update to the prior assessment completed in 2004 and documented in the "Root River Outfall and Streambank Erosion Assessment Report" (AECOM, formerly Earth Tech, January 2005). The assessment was accomplished by identifying, characterizing, and mapping current erosion problems associated with the 50-plus stormwater outfalls and hydromodifications such as riprap, concrete, and retaining walls, and associated erosion problems along the streambanks of the Root River. This is the second full assessment of the Root River streambank and is critical for monitoring changes in erosion and streambank conditions throughout time. The baseline data collected in 2004 and this assessment are useful to assessing erosion areas over time, in addition to measuring the effectiveness of past best management practices and streambank stabilization projects. The prior report has also been helpful as a planning tool to guide expenditure of City funds to stabilize streambank reaches and outfalls in the most cost effective manner and in obtaining grant funding to cost share in those improvements.

1.1 Background

The Root River Watershed covers approximately 200 square miles of Southeastern Wisconsin. The study area includes approximately 14 miles of streambank within the municipal boundary of the City of Racine, which equates to roughly seven miles of evaluation along the left and right banks. "Right" and "left" bank always assumes an orientation of looking downstream. The project limits include the right bank of the river at the dog park and the portion of the river that flows through Johnson Park. The River then leaves the City limits and re-enters the City upstream of the Horlick Dam. The river leaves the City again, downstream of Horlick Dam and re-enters the City in Colonial Park. It then flows through the City to Racine Harbor and its confluence with Lake Michigan. The study area, along with the storm sewer outfalls, is presented on Figures 1-1 and 1-2.

1.2 Data Collection

Field data collection and assessments were completed on July 11-12, August 22 in 2012, May 8-9, May 13, May15, June 4, September 17, and September 27 in 2013. AECOM visually inspected the streambanks within the study area to document their condition. The location of the vast majority of assessment points, both streambank and outfall, were recorded with a handheld Global Positioning System (GPS) unit.

1.3 Data Analysis Methodology and Findings

For this project, four methods and factors of evaluating erosion and erosion potential were utilized. These methods and factors included the Bank Erodibility Hazard Index (BEHI) and Pfankuch Channel Stability Analysis, visual observations, and adjacent land use. These methods are consistent with the methods used in the 2004-2005 assessment. Data necessary to complete these assessment methods were collected at each of the same assessment points used in the 2004-2005 assessment. The results of the four rating methods were combined to develop an overall erosion rating for each stream assessment point. Each criterion was given a different weighting based upon how critical each rating is on determining the erosion potential of each location.

Once these assessments were completed, the resultant rating for each point was compared to its representative site location. Then, reviewing the ratings that were generated from these sites, and the experience developed in the 2004-2005 assessment, the assessment team's vision could be calibrated to do complete visual assessments for the remaining portions of the river.

The areas with the highest erosion/erosion potential include:

- Small section of failing bulkhead wall along right bank on private property adjacent to Spring Street, across from Lincoln Park,
- Areas south of Lincoln Park along right bank and immediately upstream of the Wisconsin Department of Natural Resources (WDNR) Steelhead Facility, (Note – the City currently has a project in design to address this area)
- Four small isolated areas, ranging in length from 25 to 100 feet, along both banks within Colonial Park,
- Areas within Johnson Park:
 - within the golf course, both banks adjacent to the western cart path bridge at hole #11, and areas immediately upstream of the western cart path bridge,

(Note - a stabilization project for this area was completed in the summer/fall of 2013, immediately after the assessment),

- within the golf course, right bank adjacent hole #10,
- approximately 400 feet downstream of the eastern cart bridge (outside of golf course limits), mainly right bank with small portion of left bank,
- approximately 2,500 feet downstream of the eastern cart bridge, along right bank (outside of golf course limits),

There are other areas that received medium to high erosion/erosion potential ratings. Some of these have other factors that should be considered when identifying critical areas. These other areas, and their respective factors, include:

 Portion of the bulk headed section along right bank within private property (Azarian Marina, north of the intersection of Villa and Water Streets. This area is a high use (boat docks) and high profile area which could be incorporated in future riverwalk improvements. • Portion of the non-bulk headed section along the left bank within private property (Case Corporation) southeast of the intersection of Liberty and Superior Streets. This area is a high use and high profile area as it is adjacent to the City's bike/pedestrian path.

Portion of the non-bulk headed section along the left bank adjacent to Mound Avenue between Marquette and 6th Streets. Also known as the West Bluff Lookout, this area has also been identified as an area to connect/expand the City's bike/pedestrian path and add public/park space. (Note – the City/County are already in the process of planning improvements within the parcels that comprise this area),

- River bend within Washington Park, northwest of Park High School, along both banks. This
 area has moderate to high erosion, along with erosion on ravine bluffs, and erosion/damage
 to major storm sewer outfalls. This area is a high use and high profile area that is within a
 public park and golf course, and is adjacent to one of the City's high schools. (Note the
 City currently has a project in design to address this area.)
- There are several small isolated areas within Island and Lincoln Parks that have moderate to high erosion. Many of these are the result of foot traffic (e.g. anglers) accessing the river which have damaged the banks. There are also specific areas where trees are at risk of toppling resulting in ripped banks and flow blockage.

The outfall condition data were evaluated to determine the overall condition of the outfall and surrounding streambank. The assessment of each outfall included the condition of the outfall and the amount of sediment buildup within the outfall. Several outfalls had corrosion (metal), cracked (concrete), or had significant sediment accumulation. Outfalls exhibiting one of these conditions could still be classified with a fair condition rating. However, there were seven outfalls that resulted in a poor condition rating.

1.4 Recommendations

Based upon the analysis completed for this project, there are a total of six high erosion areas located along the Root River within the City. These areas do not take into account costs or public property ownership.

Five additional areas, which have moderate to moderate-high erosion were also identified as potential project sites because they have other important criteria such as key public access points, high visibility, or provide connectivity to the overall river corridor.

Recommendations presented in this report were designed to address short-term and long-term needs. The recommendations include combinations of techniques to satisfy unique site-specific requirements.

Installation of fiber rolls, stabilization seed mix and live cuttings would be suitable for shallow banks that are slightly eroded with more bare soil and some undercutting evident at the toe, as well as at intact retaining walls where toe scour is apparent. In areas where the banks are less than four feet in height and there are no site constraints at the top of bank, regrading the slope and installing fiber roll, stabilization seed mix and cuttings is recommended. If there is adequate lateral area to regrade banks that are five to six feet high, this treatment can also be used. Where scour at the toe is more prominent, stone or A-Jacks could be installed at the toe, along with erosion control blanket, seeding and cuttings. Installation of geogrids with stone, gabions, or A-Jacks are possible solutions for repairing these banks, where maintaining steep slopes with minimal property loss is a concern. J-

Hook vanes could be placed in the stream to reduce the stresses on the bank, along with providing fish habitat. Trees that need to be removed for bank regrading could be used as root wad structures

for bank protection and fish habitat. Cross vanes can also be used to direct the flows away from the streambank and toward the center of the stream.

Seven outfalls were identified as being in poor condition. These outfalls are either rusted and crushed, or cracked and destroyed. These outfalls should be replaced and additional protection, such as riprap or wing walls, should be placed around the outfalls.

2.0 Introduction

2.1 Background

The Root River Watershed covers approximately 200 square miles of Southeastern Wisconsin. The Root River originates in New Berlin in Milwaukee County, and flows 43 miles through Milwaukee and Racine Counties to empty into Lake Michigan in the City of Racine.

Sections of the Root River are considered quality fisheries. In the spring and fall, migrating chinook salmon, coho salmon, brown trout, and rainbow trout can be observed at the Root River Steelhead facility in Lincoln Park in Racine. The watershed has suffered from sedimentation from construction sites and agricultural practices, channel alterations, nutrient enrichment, and streambank erosion. The Root River is listed as a 303(d) stream, with phosphorus sited as primary pollutant of concern causing water quality use restrictions. From below the Horlick Dam (River Mile 5.82) to Lake Michigan, PCBs are also identified as causing contaminated fish tissue.

The City was awarded an Urban Nonpoint Source and Stormwater Planning Grant from the Wisconsin Department of Natural Resources (WDNR) to conduct a streambank assessment of the Root River. The grant funded preliminary data collection, fieldwork, collaboration among stakeholder, data analysis and map production, and the preparation of draft and final reports.

This is the second full assessment of the Root River streambank and is critical for monitoring changes in erosion and streambank conditions throughout time. The City of Racine (the City) conducted a streambank and outfall assessment that was completed in 2004, the "Root River Outfall and Streambank Erosion Assessment Report" (AECOM, formerly Earth Tech, January 2005). That report has been useful as a planning tool to prioritize needs and guide expenditure of City funds to stabilize outfalls and streambank reaches in the most cost effective manner and in obtaining grant funding to cost share in those improvements.

Since 2005, several major storm events have occurred. The City desired to reassess the river to determine changes in conditions due to overall river dynamics and the impacts of the major storm events. The reassessment subsequently allows the opportunity to re-prioritizing stream segments for future stabilization and erosion control projects.

The study area includes approximately 14 miles of streambank, which equates to roughly seven miles of evaluation along the left and right banks. This includes the right bank (looking downstream) of the river at the dog park and the portion of the river that flows through Johnson Park. The River then leaves the City limits and re-enters the City upstream of the Horlick Dam. The river leaves the City again, downstream of Horlick Dam and re-enters the City in Colonial Park. It then flows through the City to Racine Harbor and its confluence with Lake Michigan.

The riparian area along the river includes wooded, residential, commercial, and industrial areas. The commercial and industrial areas are primarily located near the mouth of the river and Racine Harbor.

Channel slopes vary throughout the project area from 0.003 to 3.0 percent. However, the average slope of the channel is approximately 0.1 to 0.2 percent (WDNR, 2003). The steeper the channel slope, the greater the stream velocities and the greater scouring capacity the stream will have.

2.2 Goals and Objectives

There is significant bank erosion in many reaches of the Root River project area. Subsequently, there are also locations of significant sediment deposition. This instability can be attributed to several factors, including high or "flashy" flow rates resulting from the urbanized watershed, and limited and/or encroached riparian buffers. These conditions have resulted in the degradation of the water quality and riparian health in and along the Root River. The Root River, in 1979, was one of the first watersheds in the state to be part of the Wisconsin Department of Natural Resources Priority Watershed Program and is listed on Wisconsin's Section 303(d) list of impaired waterbodies. Erosion can also threaten municipal infrastructure and reduce overall quality of life in the City as the river, with its many parks, is seen as a significant amenity to the public.

The primary goal of this project was to develop an updated assessment of the streambank and outfall conditions along the Root River in the City of Racine by identifying, characterizing, and mapping current conditions of streambank along the seven miles of river, and 50-plus stormwater outfalls. Hydromodifications, such as riprap, concrete, and retaining walls, were also noted and assessed. Comparison of current conditions to conditions observed in the 2004-2005 assessment also guided the new ratings in this report. This assessment is critical for monitoring changes in erosion and streambank conditions throughout time and prioritizing areas which should be a focus for future stabilization project. This prioritization can also be used as a tool for the City in planning future Capital Improvement Plan budgets and to aid in securing continued grant funds to cost share in future projects

Secondary goals include assessing the condition and success of previous City streambank stabilization projects and help determine ways future projects can be improved.

There are several ongoing or completed studies and projects along this section of the Root River. The WDNR, Southeastern Wisconsin Regional Planning Commission (SEWRPC), City, Root-Pike Watershed Initiative Network (WIN), Root River Council (through RootWorks), and other organizations are actively working on monitoring, assessing or restoring various portions of the river within the study area.

3.1.1 WDNR Stream Classification

In November 2003, the WDNR completed the "Lower Root River Stream Morphology Assessment". This project assigned a Channel Type score to individual stream reaches within specific walkable portions of the Root River. The reaches surveyed were from Island Park in the City, upstream to the mouth of Hoods Creek in Johnson Park. In addition to classifying the reaches, the WDNR also recommended fish habitat structures appropriate to each channel type.

The survey information and stream reach classifications completed during this WDNR study were incorporated into the erosion assessment analysis as appropriate.

3.1.2 City of Racine Streambank Stabilization Projects

The City of Racine has conducted several streambank stabilization projects over the years. At the time of the writing of this report, the City was substantially complete with recent projects on the Root River and Hoods Creek, a tributary to the Root River, in Johnson Park. Two other projects were recently contracted by the City for design in Washington Park and near Lincoln Park upstream of the fish weir. Table 3-1 lists the various streambank projects completed, underway, or planned by the City of Racine since 2005.

3.1.3 Other Projects

At the time this assessment was being completed, SEWRPC was in the process of developing a Root River Watershed Restoration Plan. As described on the SEWRPC website, the plan "will provide specific, targeted recommendations to address a set of focus issues related to conditions in the watershed. Through the input of the Root River Restoration Planning Group—which includes representatives from county and municipal governments within the watershed, MMSD, the Racine Wastewater Utility, the Wisconsin Department of Natural Resources, Sweet Water, Root-Pike WIN, and others representing a broad range of interests within the watershed—four major focus areas emerged for this watershed restoration plan: water quality, recreational use and access, habitat conditions, and flooding."

The Root-Pike Watershed Initiative Network (WIN) continues to be involved with projects that support the improvement of the Root River. These include educational, environmental monitoring, invasive species control, and BMP (e.g. rain garden) construction projects.

Root River Council has developed an Urban River Revitalization Plan and the Rootworks plan (2012). The later focuses on improvement adjacent to the downtown portions of the river.

4.0 Data Collection

Field data collection and assessments were completed on July 11-12, August 22 in 2012, May 8-9, May 13, May15, June 4, September 17, and September 27 in 2013. AECOM visually inspected the streambanks within the study area to document their condition. The location of the vast majority of assessment points, both streambank and outfall, were recorded with a Trimble GeoXH handheld Global Positioning System (GPS) unit. During the course of fieldwork, photographs were taken to further document the existing site conditions. Data collected for analysis of the outfalls and the streambank condition are described below.

4.1 Streambank Data and Analysis Methodology

For this project, four methods and factors of evaluating erosion and erosion potential were utilized. These methods and factors included the Bank Erodibility Hazard Index (BEHI), Pfankuch Channel Stability Analysis, visual observations, and adjacent land use. These methods are consistent with the methods used in the 2004-2005 assessment. Data necessary to complete these assessment methods were collected at each of the same assessment points used in the 2004-2005 assessment.

As part of the four methods, several streambank criteria were recorded to evaluate the condition of the streambank. These criteria included:

- Average Width
- Average Depth
- Bank Height
- Bankfull Height
- Bank Angle
- Water Velocity
- Water Clarity
- Water Level
- Stream Substrate and Percentages
- Channel Sinuosity
- Pool Depth
- Riffle Pool Sequence
- Canopy Cover
- Riparian Composition and Percentages
- Bank Material
- Bank Modification Type, Height and Length
- Root Depth

- Root Density
- Bank Slope Gradient
- Mass Wasting
- Debris Jam Potential
- Vegetative Bank Protection
- Channel Capacity
- Bank Rock Content
- Obstructions to Flow
- Cutting
- Deposition
- Rock Angularity
- Brightness
- Consolidation
- Bottom Size Distribution
- Scouring and Deposition
- Aquatic Vegetation

In addition, field notes were entered and photographs were taken along the way to further document existing streambank conditions.

4.2 Outfall Data

AECOM visually inspected the outfalls along the Root River within the study area to document the condition of the outfall and the surrounding streambank. The location of each identified outfall was recorded with the GPS unit (Figures 1-1 and 1-2).

Several municipal outfalls, including RR41, RR42, RR44, RR55 and RR59 were not located. These outfalls are either submerged, buried, or inaccessible. A concrete plate covered outfall RR50.

Several outfalls were evaluated, but due to access problems or dense tree canopy, were not GPS located, rather inserted in the map based on previous locates or City system map data. Outfalls not included on the City's stormwater outfall map were recorded and evaluated as private outfalls, using a "P" as a prefix (e.g. P04), instead of the "RR" which is used by the City to identify municipal outfalls along the Root River.

Several outfall characteristics were recorded to evaluate the condition of the outfall. These criteria included:

- Outfall Ownership (Municipal or Private)
- Outfall Size
- Outfall Material
- Outfall Condition (Good, Pitted, Cracked, Crushed, Rusted, Corroded)
- Sediment Accumulation
- Flow
- Flow Appearance

Photos of each outfall were also collected to further document existing outfall conditions. The outfall condition and sediment accumulation data were then evaluated to determine the overall condition of the outfall and surrounding streambank.

5.0 Data Analysis

5.1 Streambank Erosion Analysis

Streambank erosion occurs as a result of numerous processes such as surface erosion, mass wasting, saturation, freeze-thaw, and dispersion. Erosion hazard rating procedures have been developed that characterize a variety of streambank conditions into numerical indices of the potential for bank erosion (Rosgen, 1994, 1996, 1998). The ability of a streambank to resist erosion is determined by several factors. These include:

- The ratio of streambank height to bankfull stage
- The ratio of riparian vegetation rooting depth to streambank height
- The degree of rooting density
- The composition of streambank materials
- Streambank angle
- Bank material stratigraphy and presence of soil lenses
- Bank surface protection provided by debris and vegetation

For this project, four methods and factors of evaluating erosion and erosion potential were utilized in rating the specific assessment points. These methods and factors included a BEHI analysis, Pfankuch rating, visual observations, and adjacent land use.

5.1.1 BEHI Analysis

The bank-erodibility hazard index (BEHI) rating guide, developed by Dr. Dave Rosgen, assists with the evaluation of bank erosion potential. The guide incorporates an index value for the ratio of bank height to bankfull height, ratio of root depth to bank height, root density, bank angle, surface protection, bank materials, and stratification. After index values are assessed, an erosion potential rating is determined. A sample BEHI worksheet and rating guide are included in Appendix A. The BEHI ratings for each stream assessment point are shown on Table 5-1.

5.1.2 Pfankuch Rating

The Pfankuch channel stability index is also used to evaluate channel stability, (Pfankuch, 1975). The method includes 15 categories evaluated for one of four levels of stability (excellent, good, fair, or poor). Each level corresponds to a numeric index value; values for the categories are summed, and the total corresponds to a Pfankuch rating of good, fair, or poor. A sample Pfankuch rating worksheet is included in Appendix B.

This rating evaluates the streambanks in three separate sections: upper bank, lower bank, and channel bottom. The upper bank is considered the portion of the channel above the normal high water line. The lower bank is from the normal high water line to the water's edge during the summer

low flow period. The channel bottom is the portion of the channel that is submerged during the majority of the year. The Pfankuch ratings for each stream assessment point are shown on Table 5-2.

5.1.3 Visual Observations

Visual observations of the existing streambank conditions were used to supplement the erosion and stability rating methods. Areas of existing erosion were rated high, whereas areas with shallow banks and heavy vegetation were rated low. The visual observation ratings for each stream assessment point are shown on Table 5-3.

5.1.4 Adjacent Land Use

Adjacent land use was also evaluated to determine the potential effect of land use on the condition of the streambank. Areas that are heavily developed and contain large amounts of impervious areas (buildings, parking lots, etc.) often cause erosion of the streambank due to large amounts of runoff that is unable to infiltrate and has no vegetation to slow the rate of flow across the land surface and over the streambank. Heavily vegetated and wooded areas slow down runoff and allow some infiltration, thus reducing the potential for erosion along the streambank. The adjacent land use ratings for each stream assessment point are shown on Table 5-4.

5.2 Erosion Rating

The results of the four ratings described above were combined to develop an overall erosion rating for each stream assessment point. Each criterion was given a different weighting, based upon how critical each rating is on determining the erosion potential of each location. Table 5-5 illustrates the weighting for each rating criteria.

The BEHI rating is considered the most representative of the rating systems, and is therefore given the highest weighting. Adjacent land use, although a factor in erosion and erosion potential, has the lowest weighting.

During the 2012/2013 field survey, each of the initial points from the 2004-2005 study were visited and reassessed to compare the present condition to that previously documented. Each point was then assigned a new erosion hazard potential rating. Then, reviewing the ratings that were generated from these sites, and the experience developed in the 2004-2005 assessment, the assessment team's vision could be calibrated to complete visual assessments for the remaining portions of the river.

Each visual assessment point was recorded with the GPS unit. The points were processed in a geographic information system to develop delineations of specific assessment ratings.

These stream assessment locations and ratings are shown on Figures 5-1 through 5-5. Bulkheaded areas were also assigned a rating based on visual assessment, even though the streambank assessment criteria are not applicable to bulkheaded banks. Only visual assessments were completed for the bulkheaded sections.

5.3 Outfall Assessment

The assessment of each outfall included the condition of the outfall, the amount of sediment buildup within the outfall, and erosion adjacent to the outfall and from the outfall's storm water flow.

For the overall outfall assessment rating, if both outfall condition columns were good and there was little or no sediment buildup, the outfall was considered in very good condition. If one outfall condition column had a poor rating (cracked, pitted, rusted), but the second condition column was good and there was little or no sediment buildup, then the outfall was rated in good condition. If both condition assessments were poor or there was one poor condition assessment, and there was moderate erosion adjacent to the outfall, the outfall was rated as fair. If both condition assessments were poor, and there was significant erosion around the outfall, then the outfall was rated poor. Also, if the outfall was crushed, the outfall rating was poor. Table 5-7 shows the outfall assessment ratings. Figures 5-1 through 5-5 illustrate the overall ratings for each outfall.

5.4 Photo Documentation

Photos were taken to document erosion areas along the streambank and outfalls. Photo locations and approximate orientations are shown in Figures 5-6 through 5-25. Photo logs are included in Appendix C.

5.5 Comparison to the 2004-2005 Assessment

Figures 5-26 through 5-30 present the 2013 condition assessment alongside the assessment from 2004-2005. In those figures, the inner rating lines are the 2013 ratings, while the outer lines are the 2004-2005 ratings. In general, most areas that received a moderately high rating in 2004-2005 but did not present a noticeable change in 2013 were downgraded to a moderate erosion rating. There were some areas that presented worse erosion since 2004-2005, but overall, there were more areas that had little to no change since 2004-2005. Other factors impacting differences in ratings include:

- Subjectivity of assessor In the 2004-2005 assessment, three people conducted the
 assessment. One of those three people also worked on the 2013 assessment. As a result,
 for portions of the study area, the person conducting the 2013 assessment could be different
 than the 2004-2005 assessment.
- In the 2013 assessment, the assessor had the ability to use the experience from both the 2004-2005 assessment and current assessment in assigning ratings, whereas the 2004-2005 assessment had less to reference and compare.
- Conditions at the time of assessment The extent of vegetative cover and river stage at the time of assessment can impact the amount of bank exposed, and the resultant perception of conditions.

6.0 Conclusions and Recommendations

6.1 High Rated Erosion Areas

Based upon the analysis completed for this project, the areas with the highest erosion/erosion potential are listed below and presented in Figures 5-1 to 5-5.

ID	Location	Description	Total Bank Length
JP1	Johnson Park	Area within the golf course, right bank adjacent to golf hole #10. Contains steep failing banks and exposed soil.	125 ft
JP2	Johnson Park	Approximately 400 feet downstream of the eastern cart bridge (outside of golf course limits), mainly right bank with small portion of left bank. Contains steep failing banks and exposed soil along with high bluff on right bank.	1,100 ft
JP3	Johnson Park	Approximately 2,500 feet downstream of the eastern cart bridge (outside of golf course limits), along right bank. Contains steep failing banks and exposed soil.	80 ft
CP1	Colonial Park	Four small isolated areas, ranging in length from 25 to 100 feet, along both banks within Colonial Park. Contains steep failing banks and exposed soil.	225 ft
SS1	Along Spring Street, south of Lincoln Park	Areas south of the park along right bank and immediately upstream on the Wisconsin Department of Natural Resources (WDNR) Steelhead Facility. The majority of this section is owned by the City, but portions are privately owned. Contains steep failing banks and exposed soil. (Note – the City is already in process of designing improvements in this area with construction planned in 2014.)	625 ft
SS2	Along Spring Street, south of Lincoln Park	A small section of failing bulkhead wall along right bank on private property adjacent to Spring Street, across from Lincoln Park	40 ft

Note that areas within the Johnson Park golf course, adjacent to the western cart path bridge at golf hole #11, contained steep failing banks and exposed soil at the time of the assessment, and had a resultant high erosion rating. It also had a high rating in the 2004-2005 assessment. A stabilization project for this area was completed in the summer/fall of 2013, immediately after the assessment, and is therefore not included as one of the high rated areas in this report.

There are other areas that received medium to high erosion/erosion potential ratings. Some of these have other factors that should be considered when identifying important areas. These other areas, and their respective additional factors, include:

ID	Location	Description	Total Bank Length
AM1	Azarian Marina	Portion of the bulk headed section along right bank within private property (Azarian Marina, north of the intersection of Villa and Water Streets. This area is a high use (boat docks) and high profile area which could be incorporated in future riverwalk improvements.	550 ft
CC1	Case Corporation	Portion of the non-bulk headed section along the left bank within private property (Case Corporation) southeast of the intersection of Liberty and Superior Streets. This area is a high use and high profile area as it is adjacent to the City's bike/pedestrian path.	500 ft
MA1	Mound Avenue	Portion of the non-bulk headed section along the left bank adjacent to Mound Avenue between Marquette and 6 th Streets. Also known as the West Bluff Overlook, this area has also been identified as an area to connect/expand the City's bike/pedestrian path and add public/park space. (Note – the City/County are already in process of planning improvements in the parcels that comprise this area),	1,500 ft
WP1	Washington Park	River bend within Washington Park, northwest of Park High School, along both banks. This area has moderate to high erosion, along with erosion on ravine bluffs, and erosion/damage to major storm sewer outfalls. This area is a high use and high profile area that is within a public park and golf course, and is adjacent to one of the City's high schools. (Note – the City is already in process of designing improvements in this area with construction planned in 2014.)	1,200 ft
IL1	Island and Lincoln Parks	There are several small isolated areas within Island and Lincoln Parks that have moderate to high erosion. Many of these are the result of foot traffic (e.g. anglers) accessing the river which have damaged the banks. There are also specific areas where trees are at risk of toppling resulting in ripped banks and flow blockage.	250 ft +/-

River systems are dynamic, and therefore conditions can change in the future where a lower rated area may become a priority.

In prioritizing these areas for future streambank stabilization work, several factors should be taken into account. These include total overall rating, property ownership, protection of infrastructure or parks, potential stream improvement, and cost. At this time, there are no obvious threats to safety of the public, or damage to dwellings or infrastructure in the high-rated sections. Stabilizing these sections of stream will improve the aesthetics, riparian habitat, and water quality of the river.

When considering a stabilization construction project, reference to this report should be made in conjunction with a field verification of current conditions, along with consideration of project specific goals, and criteria of any grant program being pursued.

6.2 Stabilization Methods

The 2-year discharge event occurs with sufficient frequency and with sufficient energy to have a dominant impact on the channel forming process. Attempts to reconfigure the channel itself should focus on designs around the 2-year discharge. This will require corrective strategies to incorporate one or all three of the following: armoring of the channel with stone and/or vegetation, creating a floodplain bench at the 1.5 to 2-year discharge level, deflecting the erosive forces away from the eroding banks. Stabilization will have to withstand the forces of the extreme flood flows (e.g. the 100-year discharge).

The methods applied to stabilize streambanks should be based on site-specific criteria such as nature and extent of erosion, stream dynamics, adjacent land use, soils, topography, and proximity to private property, structures, trees, and infrastructure. The general strategy in designing a streambank stabilization solution is to stabilize the toe of the slope and then slope and vegetate the bank. Alternative streambank stabilization practices are listed in Table 6-1.

Bioengineering solutions utilize living plant and/or organic materials or a combination of these materials and engineered products. The plant material portion establishes a root system that binds to the surrounding soil matrix and/or the engineered elements. While these methods are often laborintensive to install, they often provide immediate bank protection and with time, long-term protection as the installation strengthens from further root growth. In addition, bioengineering solutions can be cost-effective, ecologically sensitive, improve water quality and wildlife habitat, and return the stream to a more natural appearance without adversely affecting the neighboring property.

Life expectancy for bioengineering techniques is dependent on the quality of the initial installation, the maintenance provided over the years, and the type of technique used. In general, these techniques grow stronger with each growing season, as the deep roots of the stabilizing vegetation become intertwined. If the vegetation becomes established and remains vigorous, these solutions can be effective for decades.

The following discussion highlights selected alternatives that appear to be most applicable to this project.

6.2.1 Instream Practices

Vanes or J-Hook Vanes – Vanes protect the streambank by redirecting the thalweg (deepest point of flow in the channel) away from the streambank and towards the center of the channel. They also improve in-stream habitat through scour reduction, oxygenation and cover.

Vanes are bars typically constructed of rock that are oriented upstream with angles off the bank from 20 to 30 degrees. Vanes are located just downstream of the point where the stream flow encounters the streambank at acute angles. The structure is highest next to the bank, generally starting at bankfull. The structures slope down, pointing upstream. The size of rock will



depend on the size of the stream. Flat rocks are preferred because they are easier to place and stack additional rocks on top. The length of a single vane structure can span one-half to two-thirds of the base flow channel width. The slopes of the structure can range widely from 2 to 20 percent; however,

longer, flatter structures are preferred for maximum length of streambank protection and maximum habitat creation. (NCSRI, 2003)

Cross Vanes – Cross vanes are used to provide grade control, to keep the thalweg in the center of the channel, and to protect the bank. These structures decrease near-bank shear stress, velocity and stream energy, but increase the energy in the center of the channel. The structure will establish grade control, reduce bank erosion, create a stable width/depth ratio, and maintain channel capacity, while maintaining sediment transport capacity, and sediment competence. A cross vane consists of two rock vanes and one center structure perpendicular to the flow. The center structure sets the invert grade of the streambed. Therefore, this structure can be used to raise the bed and is often used at the head of a riffle to set the elevation of the upstream pool.



6.2.2 Streambank Treatment

Vegetative Pruning and Removal - Prior to installation of bioengineered improvements, selective vegetative pruning, and removals can be performed within the project reach. The thinning of nonnative and undesirable trees and shrub species increases sunlight allowing newly planted seeds and plugs to thrive in once shade suppressed areas. This is especially important for the north-facing slopes. Trees within the riparian zone can hinder stabilization by preventing sunlight from reaching ground vegetation. Trees can also add stress to the bank by their own weight, especially when leaning or overhanging. When trees within the riparian zone are removed, stabilization and habitat functions are mitigated by plantings of deep-rooted native species that strengthen soil matrices and thrive under conditions of occasional inundation.

Trees along a stream act as visual screens and noise barriers, and enhance or create new wildlife and aquatic habitat. However, dead and damaged trees should occasionally be removed to prevent debris jams within the stream channel and further erosion from subsequent movement into the channel. This includes trees that have fallen, are split, beaver girdled, or undercut by streambank erosion. Removal of roots is not generally recommended because they often hold the streambank together and their removal would likely provide an area where further erosion can occur. Trees that are partially undercut may be toppled by high winds, where the entire root wad is torn from the bank, creating a large, unprotected cavity in the bank. In some cases, the tree is flush cut, leaving the root wad in place to maintain reinforcement of the soil, and then covered with topsoil fill, erosion control fabrics, and vegetation for additional protection and stability.

Vegetation Selection – A combination of stabilization seed mix and shrub cuttings are commonly utilized to mitigate for the loss of existing vegetation (as mentioned above). The stabilization seed mix is combined with a permanent or temporary erosion control blanket and is comprised of the following components: 1) a mix of deep-rooted riparian and native species that tolerate and thrive under occasional inundation and wet conditions while also tolerant to both sun and shade, 2) a blend of annual and perennial native wildflowers and forbs to add visual interest to the mix upon establishment, 3) a temporary cover crop of Canada wild rye to provide immediate erosion protection until the permanent seed matrix is established. Table 6-2 provides a typical seed mix and application rates that have been used successfully on other streambank stabilization projects in the Midwest.

Shrub cuttings are an integral component of bioengineering techniques. Combinations of sandbar willow (Salix exigua) and red-osier dogwood (Cornus stolonifera) can be used successfully. Willows are typically installed in sunny locations while dogwoods are installed in shaded areas. Both species are tolerant of periodic inundation and have aggressive rooting capabilities in most locations that can stabilize soils quickly.

Slope Regrading - One common method of stabilization involves slope regrading of steep eroded slopes to a stable angle of repose. Following regrading of the slope, a stabilization seed mix is applied and then covered with either permanent or temporary erosion control blanket. This type of installation can be used in combination with other stabilization techniques.



Coir Fiber Roll - Coir fiber roll is often utilized in areas experiencing stable/slight to moderate bank erosion. It is fabricated from coir, a coconut fiber with high tensile strength, moisture and nutrient retention properties, and a slow decomposition rate. As this natural fiber biodegrades plantings mature and spread, reinforcing the area around the fiber roll installation. This installation



becomes stronger and improves with age. The fiber roll units typically specified are constructed of high-density, flexible rolls of coir fiber that are tightly bound with a braided synthetic mesh, are 12-inches in diameter and 20-feet long.

Fiber roll is generally installed either by itself at the toe of bank or in combination with erosion control blanket on a regraded slope. The former may apply

to areas of stable/slight bank erosion at the toe where fiber roll is staked directly into an eroded void without trenching or excavation, other than to assure a tight fit against the bank. This application creates a naturally contoured edge that follows the existing streambank. No upslope treatment other than installation of shrub cuttings is provided.

An installation of fiber roll at the toe with erosion control blanket over a regraded slope can be applied to areas of moderate bank erosion. Fiber roll is trenched into the streambed, staked, and wired down to temporarily protect the material until the plantings become established. Permanent erosion control blanket constructed of coir fiber between polypropelene mesh fabric is then installed immediately above the fiber roll on the regraded upslope area. The bottom edge of the blanket is buried under and fastened to the fiber roll, the regraded area just upslope of the fiber then receives a stabilization seed mix, and then the blanket is rolled upslope over the seeded area and staked. Upslope and upstream blanket edges are also be buried beneath soil in a shallow trench for protection against high water flows. Shrub cuttings are then inserted into the compacted backfill material between the fiber roll and the bottom edge of the upslope area and covered in permanent erosion blanket.

Vegetated Geogrids - Vegetated Geogrids are used to restore failed or severely scoured streambanks in areas of high erosive impact. Vegetated Geogrids are used primarily in areas of very steep slopes where regrading is not possible due to structural or other obstructions. For this project, there are several locations where existing trees of value could be preserved using this technique. Vegetated Geogrids are constructed of 12-inch to 15-inch thick lifts of compacted topsoil with a seed mix of deep-rooted native grasses, wrapped in permanent erosion control fabric with live



plant material cuttings inserted between the lifts. Either A-Jacks or lunkers with riprap and compacted fill can form the base of the structure. The top of the structure blends into the existing grade at the top of bank and is constructed of temporary erosion control blanket over graded topsoil and stabilization seed mix. This method, while highly effective and often the most appropriate option, is labor and material intensive, and subsequently, are the most costly of the treatments.

Grade Control Measures – Grade controls are very similar to cross vanes, and are very effective in slowing velocities with a stream. They are often designed as drop structures (step-pool configuration) or as a series of rifflespools. Typically constructed of rock, wood, or other material, these structures are placed across the channel and anchored in the streambanks. This provides a "hard point" in the streambed that resists the erosive forces of the degradation zone, and/or reduces the



upstream energy slope to prevent bed scour. Some designs are simple notched logs across a stream or rock. Other designs strategically placed boulders, which are more difficult to handle but capable of withstanding much higher flows.

Rock Toe Protection – Rocks installed for toe protection are commonly used in moderate to severely eroded areas found typically along the outside bank of a stream bend, and along banks comprised of highly erodible soils (sand and silt). The rock is used only on the toe of the bank, keyed into the streambed and streambank, with grading and vegetation of the upper portion of the bank.



Retaining Wall Structures – Retaining walls are usually only applied when site limitations (e.g. structures and/or utilities) don't allow for other treatments. Modular block walls with mechanically stabilized earth (MSE) retaining walls with modular blocks can be a cost effective, long-term approach to repairing a severely eroded bank or replacing a failing bank structure. It has been utilized extensively under similar bank stabilization conditions, can withstand tremendous forces, and requires minimal excavation and no mortar or steel reinforcement. Other techniques include steel sheeting, or

reinforced concrete. Site specific conditions, including channel characteristics and soil conditions, should be considered when ultimately selecting a retaining wall system.

The images used in this section are from the document <u>Stream Corridor Restoration: Principles</u>, <u>Processes</u>, and <u>Practices (NEH-653)</u>, by the Federal Interagency Stream Restoration Working Group (FISRWG)(15 Federal agencies of the US gov't). GPO Item No. 0120-A; SuDocs No. A 57.6/2:EN3/PT.653. ISBN-0-934213-59-3. Additional information on streambank stabilization techniques can also be found in this document.

6.3 Recommended Treatments

Based on experience from the previous assessment and stabilization projects, and as previously stated, implementation of actual stabilization measures are site specific, taking into account the nature and extent of erosion, stream dynamics, adjacent land use, soils, topography, and proximity to private property, structures, trees, and infrastructure. Also as stated, river systems are dynamic, and therefore conditions change. What may be a feasible stabilization technique today may not be years after this document was completed. Therefore, site specific solutions are not included. The techniques discussed in the previous section are likely techniques in stabilizing the banks of the river in most of the eroded sections.

6.4 Special Features

Trees have grown in along portions of the bank to the point where they completely shade the banks and suppress the growth of ground vegetation. The lack of ground vegetation is a significant cause of erosion on portions of this stream. A strong population of native vegetation with long root systems capable of holding soil in place is essential to maintaining a stable channel. Selective tree removal along some reaches could provide additional sunlight to help establish vegetation necessary for a successful stabilization project. The removal of some existing trees could prevent further erosion and create the conditions required to stabilize the banks.

In some cases where trees are immediately at the bank, the soil around the roots has eroded during high flows in the channel. This exposure causes the tree to lose its anchor to the ground, and the tree can easily be toppled. Trees can also add stress to the bank by their own weight, especially when leaning or overhanging. The failure causes severe damage to the bank by loosening the soil and leading to further erosion. Select removal of the trees with the worse exposed roots and/or highest risk of toppling will reduce the risk of bank instability. The roots should be left intact to help stabilize the bank.

6.5 Outfall Replacements

Seven outfalls were listed on Table 5-7 as being in poor condition. These outfalls are either cracked, crushed, have pipe section sliding off, or have significant sediment accumulation. These outfalls should be considered to be cleaned, replaced, repaired, and/or augmented with additional protection, such as riprap or wing walls. Some of these activities could be incorporated into another capital improvement plan (e.g. road reconstruction, utility replacements).

6.6 Maintenance

Maintenance of installed streambank stabilization methods is essential to ensure initial and continued erosion protection. Bioengineering solutions provide increased protection over time, as the deep roots of the stabilizing vegetation become established.

The City and property owners adjacent to stabilization projects should periodically inspect the area and provide routine maintenance. Immediately following installation, the following maintenance procedures are recommended:

- Avoid trampling soil before vegetation is established.
- Maintain adequate moisture level for plants until vegetation is established.
- Protect vegetation; particularly live stakes, with fencing or other means, if damage from animals eating stakes is apparent.
- Pound any loose construction stakes holding coir fiber rolls into soil until secure.
- Replace damaged or dead live stakes and vegetation.

Routine maintenance procedures to sustain the stabilization application include the following:

- Monitor condition of application for defects.
- Monitor encroachment of exotic and invasive vegetation and remove undesirable species.
- Remove dead or damaged trees (flush cut within treatment areas) and limbs.
- Remove fallen woody material and debris from the stream.
- Repair or replace damaged stabilization material as needed.
- Do not fertilize plantings on or near the streambank.
- Do not mow within 20 feet of the top of treatment to provide buffer between the stabilization area and adjacent uses.
- Prune and selectively cut live brush to reduce shade canopy and maintain healthy plants.
- Allow stabilizing vegetation to grow unmowed throughout growing season. Mowing of temporary cover crops may be desirable to encourage growth of the native plantings and to reduce thatch buildup.
- Treat plants if infested by insects or disease.
- Remove cuttings and yard waste along or in channel.

Maintenance costs vary relative to the form of stabilization treatment applied. Maintenance costs are difficult to estimate, as they may be combined or shared with other maintenance and may also vary based on differing cycles of maintenance. For example, a 2-year to 3-year maintenance cycle would be more cost-effective than a 5-year cycle by minimizing cumulative problems.

6.7 Permitting

State, Federal, and Municipal permits may be required prior to completing construction activities. Any work related to navigable waterways, wetlands, or floodplains requires permits from one or more regulatory authorities. Applicable permits will require the project proponent to justify the project purpose and need, and evaluate practicable alternatives to avoid and minimize impacts to the environment. Depending on the nature and extent of the project, permits may require three to 12 months for approval. During the preliminary design phase, a pre-application meeting is recommended to introduce the regulatory agencies to the project. Agency review during this meeting will identify the applicable permits and expedite approval schedules.

Additional site-specific information may be required as part of the permitting process. This information includes: wetland delineation, navigability determination, ordinary high watermark (OHWM) determination, and aquatic and vegetation habitats.

Each alternative will require a similar level of permitting and agency involvement. The following is a list of applicable permits that may be required for a stabilization project:

- 1. Federal Section 404 Wetland Permits.
- State Chapter 30 Waterway Permits; NR 103 Practicable Alternatives Analysis (wetland); NR 216 Erosion Control Permit.
- 3. City NR 117 Shoreland Zoning Ordinance, Special Exemption Permit.
- 4. Construction easement for private properties.

7.0 Project Implementation

7.1 Cost Estimating Methods

The estimated implementation costs are approximate and are to be used only for long-term budgetary planning. Additional site-specific and materials data would be necessary to develop a detailed estimate. During preliminary design, the appropriate surveys and geotechnical investigations must be conducted to verify and adjust initial recommendations and projected cost of construction to reflect any changes in stream morphology since the streambank erosion assessment date.

The planning level cost estimates for various stabilization treatments are based on unit costs obtained from several sources including recent bid tabulations for similar projects and similar construction experience. The individual unit costs include materials, equipment, labor, and contractor overhead and profit where applicable, and range from \$100/ft to \$300/ft.

Table 7-1 presents estimated unit costs (material and installation only) for each stream stabilization practice considered feasible for this project. Actual costs depend on amount of excavation and grading associated with the project and the number and type of vegetation specified.

7.2 Priority Stream Segment Costs

The estimated conceptual construction costs for the priority sites are presented in Tables 7-2 through 7-12. Included in the estimates were mobilization, construction, engineering, permitting, program administration (inspection), and contingency. The cost of engineering is assumed to be 15 percent of the construction cost, and construction inspection an additional 10 percent. Permitting was estimated at five percent of construction and a contingency of 15 percent of the construction cost was included to cover unknown costs, difficult subsurface conditions, or increases in material and labor rates.

Because many of the site specific conditions are not know, it was assumed for the cost estimates that the stabilization projects would include typical bank grading, re-vegetation, and rock toe, with the exception of those projects anticipated to have retaining wall.

7.3 Outfall Replacement Costs

The estimated planning level replacement costs for the seven priority sites are presented in Table 7-13. Included in the estimates were mobilization, construction, engineering, permitting, program administration (inspection), and contingency.

7.4 Funding Opportunities

Securing funding opportunities to undertake stream stabilization projects is critical to future planning and implementation of recommendations for the Root River. Many funds are in the form of grants which are part of broad-based cooperative initiatives offered by a variety of local, state, federal, and private funding sources. Identifying funding sources is a crucial step toward effective restoration goals/objectives. Table 7-14 provides a list of funding sources that might be used to assist in funding the Root River projects.

8.0 References

- Pfankuch, Dale j., 1975. "Stream Reach Inventory and Channel Stability Evaluation". USDA Forest Service, Northern Region.
- NCSRI, 2003. *Stream Restoration. A Natural Channel Design Handbook.* Prepared by the North Carolina Stream Restoration Institute and the North Carolina Sea Grant. 2003.

Rosgen, D. L. 1994. A classification of natural rivers. Catena 22:169-199.

- Rosgen, D.L. Applied River Morphology. 1996. Pagosa Springs, Colo.: Wildland Hydrology Books.
- Rosgen, D.L. 1998. *River Restoration and Natural Channel Design*. Course Handbook. Pagosa Springs, Colo.: Wildland Hydrology.
- Rosgen, D.L. 2001. The cross-vane, w-weir, and j-hook vane structures ... their description, design and application for stream stabilization and river restoration. In *Proceedings of the Wetlands Engineering and River Restoration Conference*, Reno, Nevada, Aug. 27-31. Reston, Va: American Society of Civil Engineers.

WDNR, 2003. Lower Root River Stream Morphology Assessment. November 2003.

Federal Interagency Stream Restoration Working Group (FISRWG), <u>Stream Corridor Restoration:</u> <u>Principles, Processes, and Practices (NEH-653)</u>, GPO Item No. 0120-A; SuDocs No. A 57.6/2:EN3/PT.653. ISBN-0-934213-59-3. Tables

TABLE 3-1

HISTORICAL DESIGN / CONSTRUCTION PROJECTS

Where	Project Details	Funding
Island Park (2004)	This project is located on the left bank of the right (west) channel in Island Park immediately downstream on the bike path bridge on the north west side of Island Park. The project consisted of stabilizing 100 linear feet of the south side (left bank) of the Root River. The project consisted of regarding the bank and replacing turf grass and bare areas with native vegetation. At the toe, concrete A-Jacks were installed. A lesson learned from this project was that A-Jacks, while potentially a valid stabilization measure in some instance, have been damaged and have failed to .some degree, partly due to fishermen who have accessed the water. Traditional rip rap may be a more reliable toe measure.	This project was partially funded through a grant in the amount of \$30,000 from the Great Lakes Basin Program for Soil Erosion and Sediment Control. The balance of the project (36,500) was paid out of the City Storm Water Utility. Total project cost (design and construction) was \$66,500.
Island Park (2006)	This project is located on the left bank of the right (west) channel in Island Park immediately downstream on the foot bridge adjacent to Racine Lutheran High School. The project included grading banks and stabilizing with native plantings, along with installation of J-hook vanes. The project stabilized approximately 200 feet of bank.	

Where	Project Details	Funding
Colonial Park 2009	This project consisted of the final design and construction of a total of approximately 300 linear feet of streambank stabilization in Colonial Park, along with select cutting of several trees that were at risk of toppling (trunk/root left in place). Stabilization methods included grading a more stable side-slope and planting with seed and plugs in addition to a rock toe to protect the bank from erosion.	This project was partially funded through a Urban Nonpoint Source Grant from the WDNR. Total project cost (design and construction) was approximately \$100,000.
Johnson Park 2013	This project consisted of the final design and construction of a total of approximately 600 linear feet of streambank stabilization in Colonial Park, along with select cutting of several trees that were at risk of toppling (trunk/root left in place). Stabilization methods included grading a more stable side-slope and planting with seed and plugs in addition to a rock toe to protect the bank from erosion.	This project was partially funded through a Urban Nonpoint Source Grant from the WDNR. Total project cost (design and construction) was approximately \$100,000.
Hoods Creek 2013	Hoods Creek runs along the northeastern portion of the park. The creek, over time, has caused significant bank erosion along a portion of the golf course that is approximately 150 feet. The bank erosion threatened damage to a golf green and tee box. Because of the significant need to protect property. the bank was armored with rock.	The total project cost (design and construction) was approximately \$55,000.
Spring/Washington 2014	Anticipated work. Includes two locations: (1) approximately 500 feet on bank on the right bank immediately upstream of the Steelhead Facility, and (2)in Washington Park directly north of 12 th Street and west of Linden Avenue. Total work will likely consist of grading and stabilizing of approximately 1,000 feet of banks with native vegetation, repairing existing storm sewer outfalls, and stabilizing bluffs in Washington Park.	This project is partially funded through a Urban Nonpoint Source Grant from the WDNR and a grant from the Fund for Lake Michigan. Total project cost (design and construction) is estimated at approximately \$700,000.

BANK ERODIBILITY HAZARD INDEX

											Hazard Rating ²											
	Bank	Bank Height	Bankfull	Bank Height/	Root Depth	Root Depth/	Root	Weighted Root	Bank Angle	Height of Surface	Weighted Surface	Bank Height/	Root Depth/	Weighted Root	Bank Angle	Weighted Surface	Bank Material	BEHI				
Location	Material	(ft)	Height (ft)	Bankfull Height	(ft)	Bank Height	Density	Density	(%)	Protection	Protection	Bankfull Height	Bank Height	Density	(%)	Protection	Adjustment	Rating	Ranking			
colonial	Clay	4	3	1.33	1	0.25	80	20	75	0	0	4.8	6.5	7.2	5.4	10.0	0	34.0	20			
dogpark1	Clay	3	2	1.50	1	0.33	60	20	90	0	0	5.9	5.6	7.2	7.9	10.0	0	36.6	20			
dogpark2	Clay	4	3	1.33	1	0.25	50	13	90	0	0	4.8	6.5	8.2	7.9	10.0	0	37.5	20			
	Manmade	0.5		0.05			70					10.0	10.0	10.0		4.0		07.0				
Island park 1	Modification	25	4	6.25	1	0.04	70	3	75	20	80	10.0	10.0	10.0	5.4	1.9	0	37.3	20			
island park 2	Manmade	15	F	2.00	1	0.07	60		75	F	22	10.0	0.0	10.0	E /	E C	0	20.9	20			
Island park 2	Monmodo	15	5	3.00	1	0.07	60	4	75	5	33	10.0	8.8	10.0	5.4	5.6	0	39.8	20			
island park 2	Modification	5	4	1.25	1	0.20	20	6	60	4	80	12	7.2	8.0	2.0	1.0	0	26.2	10			
	Manmado	5	4	1.20	1	0.20	30	0	00	4	00	4.3	1.2	0.9	3.9	1.9	0	20.2	10			
island park 4	Modification	15	5	3.00	2	0.13	50	7	70	3	20	10.0	8.1	8.8	49	72	0	39.0	20			
r10sa1	Clay	5	4	1.25	2	0.10	50	20	30	0	0	4.3	4 9	7.2	2.4	10.0	0	28.9	10			
r11sa1	Clay	8	5	1.60	2	0.25	30	8	60	2	25	6.0	6.5	8.7	3.9	6.5	0	31.7	20			
	Manmade	Ŭ			_	0.20		Ŭ		_		0.0	0.0	0.1	0.0	0.0		0				
r11sa2	Modification	6	6	1.00	1	0.17	40	7	70	3	50	1.0	7.7	8.8	4.9	4.3	0	26.7	10			
r12sa1	Clay	6	4	1.50	2	0.33	70	23	30	0	0	5.9	5.6	6.8	2.4	10.0	0	30.7	20			
	Manmade																					
r12sa2	Modification	7	6	1.17	2	0.29	50	14	80	4	57	3.3	6.1	8.0	5.9	3.7	0	27.0	10			
r12sa3	Clay	6	4	1.50	1	0.17	90	15	30	0	0	5.9	7.7	7.9	2.4	10.0	0	33.9	20			
	Manmade																					
r12sa4	Modification	10	5	2.00	2	0.20	70	14	70	5	50	7.9	7.2	8.0	4.9	4.3	0	32.3	20			
	Manmade																					
r13sa1	Modification	5	4	1.25	1	0.20	70	14	80	4	80	4.3	7.2	8.0	5.9	1.9	0	27.3	10			
	Manmade																					
r13sa2	Modification	5	3	1.67	2	0.40	70	28	80	4	80	6.3	4.9	6.1	5.9	1.9	0	25.2	10			
r13sa3a	Clay	5	5	1.00	1	0.20	40	8	45	0	0	1.0	7.2	8.7	3.2	10.0	0	30.1	20			
r14sa1	Clay	5	3	1.67	2	0.40	80	32	45	3	50	6.3	4.9	5.7	3.2	4.3	0	24.4	10			
-140010	Manmade	e	F	1.20	1	0.17	70	10	80	F	02	10	7 7	0.2	5.0	1.0	0	27.6	10			
1145818	Monmodo	0	5	1.20	1	0.17	70	12	00	5	03	4.0	1.1	0.3	5.9	1.0	0	27.0	10			
r14ca1b	Modification	15	5	3.00	3	0.20	30	6	70	5	33	10.0	7.2	80	4.0	5.6	0	36.6	20			
	Manmade	15	5	3.00	5	0.20		0	10	5		10.0	1.2	0.9	4.5	5.0	0	30.0	20			
r14sa2	Modification	20	4	5.00	2	0.10	50	5	60	6	30	10.0	84	9.0	39	59	0	37.2	20			
	Manmade	20		0.00		0.10		.	00	0	00	10.0	0.4	0.0	0.0	0.0	0	01.2	20			
r14sa3	Modification	10	4	2.50	2	0.20	60	12	60	4	40	8.6	7.2	8.2	3.9	5.1	0	33.0	20			
r15sa1	Clav	6	2	3.00	1	0.17	70	12	60	0	0	10.0	7.7	8.3	3.9	10.0	0	39.8	20			
	Manmade	Ť	-	0.00							Ť			0.0	0.0		- · ·	00.0				
r15sa2	Modification	6	3	2.00	1	0.17	70	12	45	3	50	7.9	7.7	8.3	3.2	4.3	0	31.3	20			
	Manmade	-	-			-	-		-	-		-			-	-	-					
r15sa3	Modification	4	2	2.00	2	0.50	90	45	30	2	50	7.9	3.9	4.7	2.4	4.3	0	23.3	10			
r15sa4	Clay	6	2	3.00	3	0.50	80	40	45	0	0	10.0	3.9	5.1	3.2	10.0	0	32.2	20			

BANK ERODIBILITY HAZARD INDEX

									•					Hazard	Rating ²				
Location	Bank Material ¹	Bank Height	Bankfull Height (ft) ¹	Bank Height/ Bankfull Height	Root Depth	Root Depth/ Bank Height	Root Density ¹	Weighted Root Densitv	Bank Angle (%)	Height of Surface Protection	Weighted Surface Protection	Bank Height/ Bankfull Height	Root Depth/ Bank Height	Weighted Root Densitv	Bank Angle (%)	Weighted Surface Protection	Bank Material Adjustment	BEHI Rating	Ranking
r16sa1	Clay	8	5	1.60	1	0.13	30	4	80	0	0	6.0	8.2	10.0	5.9	10.0	0	40.1	30
r17sa1	Manmade Modification	6	3	2.00	1	0.17	60	10	45	3	50	7.9	7.7	8.4	3.2	4.3	0	31.5	20
	Manmade	-	_			-				-		-		_	-	_	-		
r18sa1	Modification	6	3	2.00	3	0.50	80	40	90	6	100	7.9	3.9	5.1	7.9	1.0	0	25.8	10
	Manmade																		
r19sa1	Modification	10	2	5.00	2	0.20	60	12	45	6	60	10.0	7.2	8.2	3.2	3.5	0	32.1	20
r19sa2	Clay	50	2	25.00	2	0.04	40	2	70	0	0	10.0	10.0	10.0	4.9	10.0	0	44.9	30
r20sa1	Clay	20	6	3.33	2	0.10	50	5	75	0	0	10.0	8.4	9.0	5.4	10.0	0	42.8	30
r21sa1	Bedrock	15	6	2.50	2	0.13	50	7	90	8	53	8.6	8.1	8.8	7.9	4.1	-15	22.4	10
r22sa1	Clay	6	5	1.20	2	0.33	80	27	60	0	0	4.0	5.6	6.3	3.9	10.0	0	29.8	10
r22sa2	Clay	4	2	2.00	1	0.25	80	20	75	0	0	7.9	6.5	7.2	5.4	10.0	0	37.1	20
r23sa1	Clay	12	5	2.40	1	0.08	30	3	80	0	0	8.4	8.6	10.0	5.9	10.0	0	43.0	30
r23sa2	Clay	4	3	1.33	2	0.50	60	30	60	0	0	4.8	3.9	5.9	3.9	10.0	0	28.5	10
r23sa3	Clay	3	3	1.00	1	0.33	75	25	80	0	0	1.0	5.6	6.5	5.9	10.0	0	29.0	10
r23sa4	Clay	6	6	1.00	1	0.17	50	8	80	1	17	1.0	7.7	8.6	5.9	7.7	0	30.9	20
r23sa5	Clay	5	4	1.25	2	0.40	75	30	90	0	0	4.3	4.9	5.9	7.9	10.0	0	33.0	20
r23sa6	Clay	4	3	1.33	1	0.25	60	15	80	0	0	4.8	6.5	7.9	5.9	10.0	0	35.2	20
r3sa1	Clay	3	3	1.00	2	0.67	60	40	45	0	0	1.0	3.1	5.1	3.2	10.0	0	22.4	10
r4sa1	Clay	4	4	1.00	1	0.25	70	18	75	0	0	1.0	6.5	7.6	5.4	10.0	0	30.5	20
r4sa2	Clay	3	2	1.50	1	0.33	70	23	60	0	0	5.9	5.6	6.8	3.9	10.0	0	32.1	20
r5sa1	Clay	6	3	2.00	2	0.25	90	23	33	0	0	7.9	6.5	6.9	2.6	10.0	0	33.9	20
r5sa2	Clay	5	3	1.67	1	0.20	50	10	75	0	0	6.3	7.2	8.4	5.4	10.0	0	37.4	20
r6sa1	Clay	6	4	1.50	1	0.17	50	8	75	0	0	5.9	7.7	8.6	5.4	10.0	0	37.6	20
r7sa1	Clay	4	2	2.00	1	0.25	75	19	60	0	0	7.9	6.5	7.4	3.9	10.0	0	35.7	20
	Manmade																		
r8sa1	Modification	8	7	1.14	1	0.13	70	9	45	7	88	2.8	8.2	8.6	3.2	1.6	0	24.3	10
r8sa3	Clay	5	4	1.25	2	0.40	60	24	45	0	0	4.3	4.9	6.7	3.2	10.0	0	29.1	10
r8sa2	Clay	3	3	1.00	2	0.67	80	53	80	0	0	1.0	3.1	4.1	5.9	10.0	0	24.0	10
r8sa4	Manmade Modification	5	4	1.25	1	0.20	60	12	45	5	100	4.3	7.2	8.2	3.2	1.0	0	23.9	10
r9sa1	Clay	4	3	1.33	1	0.25	75	19	30	0	0	4.8	6.5	7.4	2.4	10.0	0	31.2	20
r9sa2	Clay	5	4	1.25	2	0.40	70	28	30	0	0	4.3	4.9	6.1	2.4	10.0	0	27.8	10

Notes:

¹ Field Data ² From BEHI Worksheet

Red = Very High BEHI Rating Orange = High BEHI Rating Yellow = Moderate BEHI Rating Green = Low BEHI Rating

PFANKUCH CHANNEL STABILITY RATING

	Bank	Angle		Debris Jam	Veg_	Bank	Chann	el	Bank Roc	k Obstructions	•			Roci	<					Bottom Size	e		Aquatic	Pfankuch	Stream	Reach	
Location	(%)	Mass Wasting	Potential	Prote	ction	Capaci	ty	<20% 1-	to Flow	Cutting		Depositio	n Angula	rity	Brightnes	SS	Consolidat	tion	Distrib_		Scouring/ Deposition	Vegetation	Rating	Гуре	Condition	Ranking
				Moderate	70-90%+				3" or		Some		Some	Rounded		Dull/dark/st		Moderately		change is			Scarce or				
colonial	< 30%	2	Infrequent 6	to heaw 6	density	6	Adequate	2	less	B Frequent 6	intermittent	6	New Bars	8 Corners	2	ained	1	nacked	4	size	12	5-30% 12	absent 4	85	B5	EAID	10
oolollia	<0070				dononcy		710090010	-	<20% 1-			•	Now Daio	Contoid	-			puolicia	-	0120		0 00 / 0	aboont	00	20	FAIR	10
				Moderate	70-90%+				3" or	Rocks/Logs	Little or		Little or	Rounded		Dull/dark/st		Loose		Slight dist.			Present.				
dogpark1	<30%	2	No Evidence 3	to heaw 6	density	6	Adequate	2	less	3 (embed) 2	none	4	none	4 Corners	2	ained	1	assortment	6	shift	8	5-30% 12	but spotty 3	69	F5	GOOD	5
51.51									<20% 1-	(,									-		-					0000	
				Present but	50-70%				3" or	Some	Some		Little or	Rounded		Dull/dark/st	:	Moderately		Slight dist.			Present,				
dogpark2	<30%	2	Infrequent 6	Small 4	density	9	Adequate	2	less	B Present 4	intermittent	6	none	4 Corners	2	ained	1	packed	4	shift	8	5-30% 12	but spotty 3	75	F4	GOOD	5
									20-40%																		
	30-			Present but	70-90%+				3-6"	Some	Little or		Little or	Rounded		Dull/dark/st	:	Loose		No size			Scarce or				
island park 1	40%	4	No Evidence 3	Small 4	density	6	Adequate	2	class	Present 4	none	4	none	4 Corners	2	ained	1	assortment	6	change	4	<5% 6	absent 4	60	G5	GOOD	5
									20-40%																		
					<50%				3-6"	Rocks/Logs	Little or		Little or	Rounded		Dull/dark/st	:	Loose		No size			Scarce or				
island park 2	<30%	2	No Evidence 3	Absent 2	density	12	Adequate	2	class	6 (embed) 2	none	4	none	4 Corners	2	ained	1	assortment	6	change	4	<5% 6	absent 4	60	C5	GOOD	5
									<20% 1-																		
				Present but	50-70%				3" or	Rocks/Logs	Little or		Little or	Rounded		Dull/dark/st		Loose		No size			Scarce or				
island park 3	<30%	2	No Evidence 3	Small 4	density	9	Adequate	2	less	3 (embed) 2	none	4	none	4 Corners	2	ained	1	assortment	6	change	4	<5% 6	absent 4	61	B5	GOOD	5
									<20% 1-																		
				Present but	50-70%				3" or	Some	Little or		Little or	Rounded		Dull/dark/st		Loose		No size			Scarce or				
island park 4	<30%	2	No Evidence 3	Small 4	density	9	Adequate	2	less	B Present 4	none	4	none	4 Corners	2	ained	1	assortment	6	change	4	<5% 6	absent 4	63	G5	GOOD	5
									<20% 1-	_																	
10 1				Present but	50-70%				3" or	Rocks/Logs	Little or		Little or	Rounded	_	Dull/dark/st		Loose	~	No size		50/	Scarce or				
r10sa1	<30%	2	No Evidence 3	Small 4	density	9	Adequate	2	less	3 (embed) 2	none	4	none	4 Corners	2	ained	1	assortment	6	change	4	<5% 6	absent 4	61	F5	GOOD	5
				Drogont but	50 70%				<20% 1-	Sama	Little or		Little or	Doundod		Dull/dork/ot		1.0000		No oizo			Secret or				
r11co1	-200/	2	Infroquent 6	Small 4	doncity	0	Adoquato	2		Brocont 4		4		A Corpore	2	Duil/dark/st	1	LOUSE	6	NU SIZE	4	5 20% 12	Scarce of	72	P6	FAID	10
111541	<30%	2		Siliali 4	uensity	9	Auequate	2		Fieseni 4	none	4	none	4 Comers	2	airieu	•	assonment	0	change	4	5-30 % 12	absent 4	12	65	FAIK	10
				Present but	50-70%				3" or	Some	Little or		Little or	Rounded		Dull/dark/st		Loose		Nosize			Scarce or				
r11sa2	< 30%	2	No Evidence 3	Small 4	density	9	Adequate	2	less	B Present 4	none	4	none	4 Corners	2	ained	1	assortment	6	change	4	5-30% 12	absent 4	69	G5	COOD	5
	10070	_			donony		7.00900.00	-	20-40%				nono		-	diriod		doooninoni	-	onango	· ·	0 0070				GOOD	Ŭ
				Present but	70-90%+				3-6"	Some	Little or		Little or	Rounded		Dull/dark/st		Moderately		Slight dist.			Scarce or				
r12sa1	<30%	2	No Evidence 3	Small 4	density	6	Adequate	2	class	Present 4	none	4	none	4 Corners	2	ained	1	packed	4	shift	8	<5% 6	absent 4	60	B5	GOOD	5
					,				20-40%																	0002	
				Present but	50-70%				3-6"	Some	Little or		Little or	Rounded		Dull/dark/st	:	Loose		No size			Scarce or				
r12sa2	<30%	2	No Evidence 3	Small 4	density	9	Adequate	2	class	Present 4	none	4	none	4 Corners	2	ained	1	assortment	6	change	4	<5% 6	absent 4	61	G5	GOOD	5
									<20% 1-																		
					70-90%+				3" or	Rocks/Logs	Little or		Some	Rounded		Dull/dark/st		Moderately		Slight dist.			Scarce or				
r12sa3	<30%	2	Infrequent 6	Absent 2	density	6	Adequate	2	less	3 (embed) 2	none	4	New Bars	8 Corners	2	ained	1	packed	4	shift	8	<5% 6	absent 4	65	B6	FAIR	10
							Barely		20-40%																		
	30-			Present but	70-90%+		contains		3-6"	Some	Little or		Little or	Rounded		Dull/dark/st	:	Loose		No size			Scarce or				
r12sa4	40%	4	No Evidence 3	Small 4	density	6	peak	3	class	Present 4	none	4	none	4 Corners	2	ained	1	assortment	6	change	4	<5% 6	absent 4	61	B6	GOOD	5
									20-40%	_																	
10 1				Present but	70-90%+				3-6"	Rocks/Logs	Little or		Little or	Rounded	_	Dull/dark/st		Loose	~	No size		50/	Scarce or	50	D (
ri 3sa1	<30%	2	NO Evaence 3	Small 4	aensity	6	Adequate	2		embed) 2	none	4	none	4 Corners	2	ained	1	assortment	b	cnange	4	<5% <mark>6</mark>	absent 4	56	84	GOOD	5
				Brocont but	70 000/ -				20-40%	Pooks /Logo	Little or		Little or	Pounded		Dull/dorle/-+		1,0000		Nocizo			Searce or				
r13co2	~30%	2	No Evidence 2	Small 4	density	6	Adequato	2	o-c	(embed) 2		Λ			2	ained	1	assortment	6	change	<u> </u>	~5%	absent 1	56	BG	COOD	5
113542	<30%	2		Sinaii 4	uensity	U	Auequale		class		none	4	TIONE	Comers	2	airieu		assonment	U	change	-	NJ 10	ausenii 4		00	GOOD	5
				Present but	50-70%				3" or	Some	Little or		Little or	Rounded		Dull/dark/et		Loose		No size			Scarce or				
r13sa3a	<30%	2	No Evidence	Small 4	density	q	Adequate	2	less	Present 4	none	4	none	4 Corners	2	ained	1	assortment	6	change	4	<5% 6	absent 4	63	B6	FAID	10
. 100000	-0070	-			aonony	~	, auquate	-	1000		1010	1.1	nono	. 0011013	~		1	assortment	<u> </u>	onungo	1.00	-970		30	50	FAIK	.0

PFANKUCH CHANNEL STABILITY RATING

Location	Bank (%	Angle %)	Mass Was	sting	Debris Ja Potentia	am al	Veg_B Protec	ank tion	Channe Capaci	el Bank ty Con	Rock tent	Obstruction to Flow	ns	Cutting		Deposit	ion	Rock Angula	rity	Brightnes	s	Consolidat	tion	Bottom Size Distrib_	Scouring	/ Deposition	Aquati Vegetati	on l	Pfankuch Rating	Stream Type	Reach Condition	Ranking
r14sa1	<30%	2	No Evidence	3	Present but Small	4	70-90%+ density	6	Adequate	20-40% 3-6" 2 class	6	Rocks/Logs (embed)	2	Little or none	4	Little or none	4	Rounded Corners	2	Dull/dark/st ained	1	Moderately packed	4	Slight dist. shift 8	<5%	6	Scarce or absent	4	58	B5	GOOD	5
r14sa1a	<30%	2	No Evidence	3	Present but Small	4	70-90%+ density	6	Adequate	<pre><20% 1-</pre>	8	Some Present	4	Little or none	4	Little or none	4	Rounded Corners	2	Dull/dark/st ained	1	Loose assortment	6	No size change 4	<5%	6	Scarce or absent	4	60	B5	GOOD	5
r14sa1b	<30%	2	No Evidence	3	Present but Small	4	50-70% density	9	Adequate	20-40% 3-6" 2 class	6	Rocks/Logs (embed)	2	Little or none	4	Little or none	4	Rounded Corners	2	Dull/dark/st ained	1	Loose assortment	6	No size change 4	<5%	6	Scarce or absent	4	59	B5	GOOD	5
r14sa2	<30%	2	No Evidence	3	Present but Small	4	50-70% density	9	Adequate	<20% 1- 3" or 2 less	8	Some Present	4	Little or none	4	Some New Bars	8	Rounded Corners	2	Dull/dark/st ained	1	Loose assortment	6	No size change 4	5-30%	12	Scarce or absent	4	73	F5	GOOD	5
r14sa3	<30%	2	No Evidence	3	Present but Small	4	50-70% density	9	Ample (+ increase)	<pre><20% 1-</pre>	8	Rocks/Logs (embed)	2	Little or none	4	Some New Bars	8	Rounded Corners	2	Dull/dark/st ained	1	Loose assortment	6	No size change 4	5-30%	12	Scarce or absent	4	70	F6	GOOD	5
r15sa1	<30%	2	Infrequent	6	Present but Small	4	70-90%+ density	6	Adequate	<pre><20% 1- 3" or 2 less</pre>	8	Some Present	4 i	Some	6	Some New Bars	8	Rounded Corners	2	Dull/dark/st ained	1	Moderately packed	4	Slight dist. shift 8	5-30%	12	Scarce or absent	4	77	F6	GOOD	5
r15sa2	<30%	2	No Evidence	3	Present but Small	4	70-90%+ density	6	Ample (+ increase)	20-40% 3-6" 1 class	6	Rocks/Logs (embed)	2 i	Some intermittent	6	Some New Bars	8	Rounded Corners	2	Dull/dark/st ained	1	Moderately packed	4	Slight dist. shift 8	5-30%	12	Scarce or absent	4	69	F5	GOOD	5
r15sa3	<30%	2	No Evidence	3	Absent	2	90%+ density	3	Ample (+ increase)	<20% 1- 3" or 1 less	8	Rocks/Logs (embed)	2	Little or none	4	Some New Bars	8	Rounded Corners	2	Dull/dark/st ained	1	Moderately packed	4	Slight dist. shift 8	<5%	6	Scarce or absent	4	58	F5	GOOD	5
r15sa4	####	FALSE	No Evidence	3	Present but Small	4	70-90%+ density	6	Ample (+ increase)	<20% 1- 3" or 1 less	8	Some Present	4	Little or none	4	Little or none	4	Rounded Corners	2	Dull/dark/st ained	1	Moderately packed	4	Slight dist. shift 8	<5%	6	Scarce or absent	4	59	F4	GOOD	5
r15sa5	30- 40%	4	No Evidence	3	Present but Small	4	<50% density	12	Adequate	20-40% 3-6" 2 class	6	Rocks/Logs (embed)	2	Little or none	4	Little or none	4	Rounded Corners	2	Dull/dark/st ained	1	Moderately packed	4	Slight dist. shift 8	<5%	6	Scarce or absent	4	66	F6	GOOD	5
r15sa6	<30%	2	No Evidence	3	Absent	2	70-90%+ density	6	Adequate	20-40% 3-6" 2 class	6	Rocks/Logs (embed)	2	Little or none	4	Little or none	4	Rounded Corners	2	Dull/dark/st ained	1	Loose assortment	6	No size change 4	<5%	6	Scarce or absent	4	54	F5	GOOD	5
r16sa1	<30%	2	Infrequent	6	Moderate to heavy	6	<50% density	12	Barely contains peak	40-60% small 3 cobbles	4	Some Present	4	Significant	12	Little or none	4	Rounded Corners	2	Dull/dark/st ained	1	Moderately packed	4	Slight dist. shift 8	5-30%	12	Scarce or absent	4	84	E4	FAIR	10
r17sa1	<30%	2	Infrequent	6	Present but Small	4	50-70% density	9	Adequate	20-40% 3-6" 2 class	6	Rocks/Logs (embed)	2	Little or none	4	Little or none	4	Rounded Corners	2	Dull/dark/st ained	1	Moderately packed	4	No size change 4	<5%	6	Scarce or absent	4	60	F6	GOOD	5
r18sa1	<30%	2	No Evidence	3	Absent	2	70-90%+ density	6	Adequate	20-40% 3-6" 2 class	6	Rocks/Logs (embed)	2	Little or none	4	Little or none	4	Rounded Corners	2	Dull/dark/st ained	1	Moderately packed	4	No size change 4	<5%	6	Scarce or absent	4	52	F5	GOOD	5
r19sa1	<30%	2	No Evidence	3	Absent	2	50-70% density	9	Ample (+ increase)	20-40% 3-6" 1 class	6	Rocks/Logs (embed)	2	Little or none	4	Little or none	4	Rounded Corners	2	Dull/dark/st ained	1	Moderately packed	4	Slight dist. shift 8	<5%	6	Scarce or absent	4	58	F6	GOOD	5
r19sa2	30- 40%	4	No Evidence	3	Present but Small	4	50-70% density	9	Ample (+ increase)	<20% 1- 3" or 1 less	8	Rocks/Logs (embed)	2 i	Some intermittent	6	Little or none	4	Rounded Corners	2	Dull/dark/st ained	1	Loose assortment	6	Mod. change is size 12	<5%	6	Scarce or absent	4	72	F6	GOOD	5

PFANKUCH CHANNEL STABILITY RATING

	Bank	Angle			Debris J	am	Veg_E	Bank	Channe	el	Bank F	Rock	Obstruction	ıs					Rock	< · · · · · · · · · · · · · · · · · · ·			Bottom	Size	ĺ		Aquatio	;	Pfankuch	Stream	Reach	
Location	(%	%)	Mass Was	sting	Potenti	al	Protec	tion	Capaci	ty	Cont	ent	to Flow		Cuttin	ıg	Deposit	ion	Angula	rity	Brightness	Consolidation	Distri	b	Scouring	/ Deposition	Vegetati	on	Rating	Туре	Condition	Ranking
r20sa1	30- 40%	4	No Evidence	3	Absent	2	50-70% density	9	Adequate	2	20-40% 3-6" class	6	Some Present	4	Little or none	4	Moderate	12	Rounded Corners	2	Dull, <35% bright 2	Moderately packed 4	No size change	4	<5%	6	Scarce or absent	4	68	F6	GOOD	5
r21sa1	30- 40%	4	No Evidence	3	Absent	2	50-70% density	9	Adequate	2	20-40% 3-6" class	6	Some Present	4	Little or none	4	Moderate	12	Rounded Corners	2	Dull, <35% bright 2	Moderately packed 4	No size change	4	<5%	6	Scarce or absent	4	68	F6	GOOD	5
r22sa1	30- 40%	4	No Evidence	3	Absent	2	70-90%+ density	6	Adequate	2	20-40% 3-6" class	6	Rocks/Logs (embed)	2	Little or none	4	Moderate	12	Well Rounded 2D	3	Dull, <35% bright 2	Moderately packed 4	Slight dist shift	. 8	<5%	6	Present, but spottv	3	67	F6	GOOD	5
122522	30- 40%	4	No Evidence	3	Absent	2	70-90%+	6	Ample (+	1	20-40% 3-6"	6	Rocks/Logs	2	Little or	4	Moderate	12	Rounded	2	Dull/dark/st	Moderately	Slight dist	. <u>8</u>	5-30%	12	Present,	3	70	F6	COOD	5
-02004	30-				Moderate		50-70%	0	Adamusta		<20% 1- 3" or		(onded)	2	Circificant		Little or		Rounded	2	35-65%	Loose	Slight dist		20.50%	10	Scarce or		00	P.4	GOOD	15
123581	30-	4	innequent	0	Present but	t	50-70%	9	Ample (+	2	20-40% 3-6"	0	Some	0	Some	12	Little or	4	Rounded	2	Dull/dark/st	Moderately	Slight dist		30-30%	10	Scarce or	4	90	D4	POOR	15
r23sa2	40%	4	No Evidence	3	Small	4	density 70-90%+	9	increase)	1	class <20% 1- 3" or	6	Present Some	4 i	Little or	6	none Some	4	Rounded	2	ained 1 Dull, <35%	packed 4 Moderately	shift Slight dist		<5%	6	absent Present,	4	66	В3	FAIR	10
r23sa3	<30%	2	No Evidence Frequent(lar	3	Absent Present but	2 t	density 50-70%	6	Adequate Barely contains	2	less <20% 1- 3" or	8	Present Some	4	none Some	4	New Bars	8	Corners	2	bright 2 Dull. <35%	packed 4 Moderately	shift Slight dist	8	5-30%	12	but spotty Scarce or	3	70	B6	FAIR	10
r23sa4	<30%	2	ge)	9	Small	4	density	9	peak	3	less 40-60%	8	Present	4 i	intermittent	6	Moderate	12	Corners	2	bright 2	packed 4	shift	8	5-30%	12	absent	4	89	B6	POOR	15
r23sa5	40%	4	No Evidence	3	Small	4	density	9	increase)	1	cobbles <20% 1-	4	(embed)	2	Significant	12	none	4	Corners	2	ained 1	assortment 6	change	4	<5%	6	absent	4	66	B6	FAIR	10
r23sa6	<30%	2	Infrequent	6	Present but Small	t 	50-70% density	9	Adequate	2	3" or less <20% 1-	8	Some Present	4	Significant	12	Moderate	12	Rounded 2D	3	Dull/dark/st ained 1	Loose assortment 6	No size change	4	5-30%	12	Present, but spotty	3	88	B6	POOR	15
r3sa1	<30%	2	Infrequent	6	Moderate to heavy	6	70-90%+ density	6	Adequate	2	3" or less 40-60%	8	Some Present	4 i	Some intermittent	6	Some New Bars	8	Rounded Corners	2	Dull/dark/st ained 1	Moderately packed 4	Slight dist shift	8	5-30%	12	Scarce or absent	4	79	F4	GOOD	5
r4sa2	<30%	2	No Evidence	3	Present but Small	t 4	70-90%+ density	6	Adequate	2	small cobbles	4	Some Present	4 i	Some intermittent	6	Some New Bars	8	Rounded Corners	2	Dull/dark/st ained 1	Moderately packed 4	Slight dist	8	5-30%	12	Scarce or absent	4	70	B4	FAIR	10
r5sa1	<30%	2	No Evidence	3	Absent	2	90%+ density	3	Adequate	2	small cobbles	4	Rocks/Logs (embed)	2	Little or none	4	Some New Bars	8	Rounded Corners	2	Dull, <35% bright 2	Assorted, tight pack 2	change is size	12	<5%	6	Scarce or absent	4	58	C5	GOOD	5
r5sa2	<30%	2	No Evidence	3	Present bu Small	t 4	50-70% density	9	Adequate	2	<20% 1- 3" or less	8	Some Present	4 i	Some intermittent	6	Little or none	4	Rounded Corners	2	Dull/dark/st ained 1	Loose assortment 6	Slight dist shift	. 8	5-30%	12	Scarce or absent	4	75	C6	GOOD	5
r6sa1	<30%	2	Infrequent	6	Present but Small	t 4	50-70% density	9	Adequate	2	20-40% 3-6" class	6	Some Present	4	Significant	12	Little or none	4	Rounded Corners	2	Dull/dark/st ained 1	Loose assortment 6	No size change	4	5-30%	12	Scarce or absent	4	78	B6	FAIR	10
r7sa1	<30%	2	No Evidence	3	Present but Small	t 4	70-90%+ density	6	Adequate	2	40-60% small cobbles	4	Some Present	4	Little or none	4	Some New Bars	8	Rounded Corners	2	Dull/dark/st ained 1	Moderately packed 4	Slight dist shift	. 8	<5%	6	Scarce or absent	4	62	E4	GOOD	5
r8sa1	30- 40%	4	No Evidence	3	Present but Small	t 4	70-90%+ density	6	Adequate	2	65%+ w/ Lg/ Boulders	2	Rocks/Logs (embed)	2	Little or none	4	Little or none	4	Rounded Corners	2	Dull/dark/st ained 1	Moderately packed 4	Slight dist shift	. 8	5-30%	12	Scarce or absent	4	62	B4	GOOD	5
r8sa2	<30%	2	No Evidence	3	Present but Small	t _4	70-90%+ densitv	6	Adequate	2	<20% 1- 3" or less	8	Rocks/Logs (embed)	2	Little or none	4	Little or none	4	Rounded Corners	2	Dull/dark/st ained 1	Moderately packed 4	Slight dist shift	. 8	<5%	6	Scarce or absent	4	60	B4	GOOD	5
r8sa3	<30%	2	No Evidence	3	Present bu	t _1	70-90%+	6	Adequate	2	<20% 1- 3" or	R	Some	4	Little or	4	Little or	4	Rounded	2	Dull/dark/st	Moderately	Slight dist		5-30%	12	Scarce or	4	68	R4	EAID	10
r8sa4	<30%	2	No Evidence	3	Present but Small	t	<50% density	12	Barely contains peak	3	65%+ w/ Lg/ Boulders	2	Rocks/Logs (embed)	2	Little or none	4	Little or none	4	Rounded	2	Dull/dark/st ained 1	Loose assortment 6	No size change	4	5-30%	12	Scarce or absent	4	65	B5	GOOD	5

Notes: First column under each heading is from field assessment. Second column is from Pfankuch Stability Worksheet.

Red = Poor Pfankuch Rating Yellow = Fair Pfankuch Rating Green = Good Pfankuch Rating

L:\work\60263726\300_Administration\309_Administrative_Documents\309.2_Reports\Final\City of Racine_Final_Report.doc

VISUAL RATING

Location	Ranking
colonial	4
dogpark1	4
dogpark2	8
island park 1	4
island park 2	4
island park 3	4
island park 4	4
r10sa1	4
r11sa1	4
r11sa2	8
r12sa1	0
r12sa2	4
r12sa3	4
r12sa4	4
r13sa1	4
r13sa2	4
r13sa3a	4
r14sa1	4
r14sa1a	0
r14sa1b	4
r14sa2	0
r14sa3	4
r15sa1	4
r15sa2	4
r15sa3	4
r15sa4	0
r15sa5	8
r15sa6	4

Location	Ranking
r16sa1	12
r17sa1	4
r18sa1	0
r19sa1	4
r19sa2	8
r20sa1	8
r21sa1	8
r22sa1	0
r22sa2	0
r23sa1	12
r23sa2	8
r23sa3	4
r23sa4	12
r23sa5	12
r23sa6	12
r3sa1	4
r4sa1	4
r4sa2	4
r5sa1	0
r5sa2	4
r6sa1	4
r7sa1	4
r8sa1	4
r8sa2	4
r8sa3	4
r8sa4	8
r9sa1	8
r9sa2	8

Red Orange = Yellow =

High Erosion Moderate to High Erosion

- Moderate Erosion =
- Green
- Low Erosion

=

=
TABLE 5-4

ADJACENT LAND USE

Location	Land Use	Rating	Location
colonial	Wooded	0	r16sa1
dogpark1	Wooded	0	r17sa1
dogpark2	Wooded	0	r18sa1
island park 1	Wooded	0	r19sa1
island park 2	Residential	4	r19sa2
island park 3	Wooded	0	r20sa1
island park 4	Residential	4	r21sa1
r10sa1	Residential	4	r22sa1
r11sa1	Commercial/Industrial	6	r22sa2
r11sa2	Commercial/Industrial	6	r23sa1
r12sa1	Park/open	2	r23sa2
r12sa2	Park/open	2	r23sa3
r12sa3	Wooded	0	r23sa4
r12sa4	Residential	4	r23sa5
r13sa1	Wooded	0	r23sa6
r13sa2	Wooded	0	r3sa1
r13sa3a	Park/open	2	r4sa1
r14sa1	Park/open	2	r4sa2
r14sa1a	Wooded	0	r5sa1
r14sa1b	Residential	4	r5sa2
r14sa2	Park/open	2	r6sa1
r14sa3	Residential	4	r7sa1
r15sa1	Park/open	2	r8ca1
r15sa2	Park/open	2	10381 r8sa2
r15sa3	Park/open	2	10302
r15sa4	Residential	4	10503
r15sa5	Residential	4	10584
r15sa6	Park/open	2	19581
			19932

Location	Land Use	Rating
r16sa1	Residential	4
r17sa1	Commercial/Industrial	6
r18sa1	Commercial/Industrial	6
r19sa1	Commercial/Industrial	6
r19sa2	Commercial/Industrial	6
r20sa1	Commercial/Industrial	6
r21sa1	Commercial/Industrial	6
r22sa1	Commercial/Industrial	6
r22sa2	Wooded	0
r23sa1	Wooded	0
r23sa2	Wooded	0
r23sa3	Park/open	2
r23sa4	Park/open	2
r23sa5	Park/open	2
r23sa6	Park/open	2
r3sa1	Wooded	0
r4sa1	Wooded	0
r4sa2	Wooded	0
r5sa1	Wooded	0
r5sa2	Wooded	0
r6sa1	Park/open	2
r7sa1	Park/open	2
r8sa1	Park/open	2
r8sa2	Park/open	2
r8sa3	Wooded	0
r8sa4	Park/open	2
r9sa1	Park/open	2
r9sa2	Park/open	2

....

1 -

Red	=	High Erosion
Orange	=	Moderate to High Erosion
Yellow =	=	Moderate Erosion
Green	=	Low Erosion

TABLE 5-5

WEIGHTING OF RATINGS

Boting System	Erosion Condition						
Rating System	Low Moderate		Moderate-High	High			
BEHI	0	10	20	30			
Pfankuch	5 (Good)	10 (Fair)	15 (Poor)				
Visual	0	4	8	12			
Adjacent Land Use	0	2	4	6			

TABLE 5-6 OVERALL EROSION RATINGS

Location	Overall Ranking		Overall
colonial	34	Location	Ranking
dogpark1	29	r16sa1	56
dogpark2	33	r17sa1	35
island park 1	29	r18sa1	21
island park 2	33	r19sa1	35
island park 3	19	r19sa2	49
island park 4	33	r20sa1	49
r10sa1	23	r21sa1	29
r11sa1	40	r22sa1	21
r11sa2	29	r22sa2	25
r12sa1	27	r23sa1	57
r12sa2	21	r23sa2	28
r12sa3	34	r23sa3	26
r12sa4	33	r23sa4	49
r13sa1	19	r23sa5	44
r13sa2	19	r23sa6	49
r13sa3a	36	r3sa1	19
r14sa1	21	r4sa1	29
r14sa1a	15	r4sa2	34
r14sa1b	33	r5sa1	25
r14sa2	27	r5sa2	29
r14sa3	33	r6sa1	36
r15sa1	31	r7sa1	31
r15sa2	31	r8sa1	21
r15sa3	21	r8sa2	21
r15sa4	29	r8sa3	24
r15sa5	47	r8sa4	25
r15sa6	31	r9sa1	35
		r9sa2	25

Red	=	High Erosion
Orange	=	Moderate to High Erosion
Yellow =	=	Moderate Erosion
Green	=	Low Erosion

December 2013

TABLE 5-7 OUTFALL ASSESSMENTS

Outfall	Outfall ID			Outfall	Outfall	Fracian Dating	Codimont	Flow	Flow	2013 Outfall	2005 Outfall	Commont
Ownership	OutrainID	Outrall Size (In)	Outrail Material	Condition	Condition 2	Erosion Rating	Sealment	FIOW	Appearance	Rating	Rating	Comment
PRIVATE	P01	18	Concrete	Good	Good	Moderate	None	No	NA	Excellent	Excellent	
PRIVATE	P02	30	Concrete	Good	Good	Moderate	None	No	NA	Excellent	Excellent	
PRIVATE	P03	48	Concrete	Good	Good	Moderate	None	Yes	Clear	Excellent	Excellent	
PRIVATE	P04	30	Concrete	Good	Good	Moderate	None	Yes	Clear	Excellent	Excellent	
PRIVATE	P05	54	Concrete	Good	Good	Moderate	Little	Yes	Clear	Excellent	Good	
PRIVATE	P06	60	Concrete	Good	Good	Moderate	Little	Yes	Clear	Excellent	Excellent	
PRIVATE	P08	12	Smooth Metal	Good	Good	Moderate	Little	No	NA	Excellent	Excellent	
PRIVATE	P09	12	Smooth Metal	Good	Good	Moderate	>1/4 full	No	NA	Fair	Fair	
PRIVATE	P11	12	Concrete	Corroded	Good	Moderate	None	No	NA	Fair	Fair	
PRIVATE	P11A	12	Concrete	Good	Good	Moderate	None	No	NA	Excellent	NA	
PRIVATE	P12	10	Corrugated Metal	Good	Corroded	Moderate	None	No	NA	Good	Excellent	
PRIVATE	P12A	24	Corrugated Metal	Good	Good	Moderate	None	No	NA	Excellent	NA	
PRIVATE	P12B	24	Concrete	Good	Good	Moderate	None	Yes	Clear	Excellent	NA	
PRIVATE	P12C	24	Concrete	Good	Good	Low (Bulkheaded)	None	No	NA	Excellent	NA	
PRIVATE	P13	48	Concrete	Good	Good	Low (Bulkheaded)	Little	No	NA	Excellent	Excellent	
PRIVATE	P15	24	Smooth Metal	Cracked	Good	Moderately High	>1/4 full	No	NA	Poor	Poor	
PRIVATE	P16	24	Concrete	Good	Good	Low (Bulkheaded)	None	No	Clear	Excellent	NA	
MUNICIPAL	RR01	40 x 64	Corrugated Metal	Good	Good	Moderate	None	No	NA	Excellent	Excellent	
MUNICIPAL	RR02	18	Concrete	Good	Good	Moderate	>1/4 full	No	NA	Fair	Excellent	
MUNICIPAL	RR06	27 (Failed Section)	Concrete	Cracked	Cracked	Moderate	None	No	NA	Poor	Excellent	
MUNICIPAL	RR12B	24	Concrete	Good	Good	Low (Bulkheaded)	None	Yes	Clear	Excellent	NA	
MUNICIPAL	RR14	18	Corrugated Metal	Good	Good	Moderate	None	Yes	Clear	Excellent	Excellent	
MUNICIPAL	RR15	84	Corrugated Metal	Good	Corroded	High	None	Yes	Clear	Fair	Good	
MUNICIPAL	RR16	48	Concrete	Good	Good	Moderate	1/4 full	Yes	Cloudy	Good	Good	
MUNICIPAL	RR17	30	Concrete	Good	Good	Moderate	None	Yes	Clear	Excellent	Excellent	
MUNICIPAL	RR18	48	Concrete	Good	Good	Moderate	Little	Yes	Clear	Excellent	Excellent	
MUNICIPAL	RR19	12	Concrete	Good	Good	Moderate	None	Yes	Clear	Excellent	Poor	Replaced since last assessment
MUNICIPAL	RR20	48	Concrete	Good	Pitted	Moderate	None	Yes	Clear	Good	Good	
MUNICIPAL	RR20A	24	Smooth Metal	Good	Good	Moderate	>1/4 full	No	NA	Fair	Fair	
MUNICIPAL	RR20B	15	Smooth Metal	Good	Good	Moderate	>1/4 full	Yes	Clear	Fair	NA	
MUNICIPAL	RR22	48	Concrete	Good	Good	Moderate	None	Yes	Clear	Excellent	Good	
MUNICIPAL	RR23	12	Concrete	Good	Good	Moderate	1/4 full	Yes	Clear	Good	Good	
MUNICIPAL	RR24	8	Concrete	Good	Good	Moderate	>1/4 full	Yes	Clear	Fair	Poor	Replaced since
												last assessment
MUNICIPAL	RR25	36	Concrete	Good	Corroded	Moderate	None	Yes	Clear	Fair	Good	
MUNICIPAL	RR26	12	Smooth Metal	Cracked	Crushed	Moderate	>1/4 full	No	NA	Poor	Poor	
MUNICIPAL	RR27	21	Concrete	Good	Corroded	Moderate	None	No	NA	Fair	Excellent	
MUNICIPAL	RR28	15	Corrugated Metal	Good	Good	Low	None	No	NA	Excellent	Excellent	

Outfall	Outfall ID	Outfall Size (in)	Outfall Material	Outfall	Outfall	Erosion Rating	Sediment	Flow	Flow	2013 Outfall	2005 Outfall	Comment
Ownership				Condition	Condition 2				Appearance	Rating	Rating	
MUNICIPAL	RR29	12	Corrugated Metal	Pitted	Rusted	Low	None	No	NA	Fair	Fair	
MUNICIPAL	RR30	BULKHEADED	NA	NA	NA	NA	NA	NA	NA	N/A	Poor	
MUNICIPAL	RR30B	12	Corrugated Metal	Good	Good	Moderate	None	No	NA	Excellent	NA	
MUNICIPAL	RR31	24	Concrete	Good	Good	Low	None	Yes	Clear	Excellent	Excellent	
MUNICIPAL	RR31A	18	Smooth Metal	Good	Corroded	Moderately High	None	No	NA	Good	N/A	
MUNICIPAL	RR31B	15	Corrugated Metal	Good	Good	Moderately High	None	No	NA	Excellent	NA	
MUNICIPAL	RR32	15	Corrugated Metal	Good	Good	Moderately High	None	Yes	Clear	Excellent	Excellent	
MUNICIPAL	RR33	24	Concrete	Good	Corroded	Moderately High	None	Yes	Clear	Fair	Good	
MUNICIPAL	RR34	24	Concrete	Good	Good	Moderately High	None	No	NA	Excellent	Excellent	
MUNICIPAL	RR35	34 x 52	Concrete	Good	Good	Moderate	None	Yes	Clear	Excellent	Excellent	
MUNICIPAL	RR36	40 x 40	Concrete	Good	Pitted	Moderate (Bulkheaded)	Little	Yes	Clear	Fair	Good	
MUNICIPAL	RR37E-1	60	Corrugated Metal	Cracked	Corroded	Moderate	None	Yes	Clear	Poor	NA	
MUNICIPAL	RR37E-2	108	Concrete	Cracked	Corroded	Moderate	None	Yes	Clear	Poor	NA	
MUNICIPAL	RR37w	84	Corrugated Metal	Good	Corroded	Moderate	None	Yes	Clear	Good	Good	
MUNICIPAL	RR38	30	Concrete	Good	Good	Moderate	>1/4 full	No	NA	Fair	Fair	
MUNICIPAL	RR39	27	Concrete	Good	Good	Moderate	None	Vos	Clear	Excellent	Excellent	
	RR40	60	Concrete	Good	Pitted	Moderate	None	Vos	Clear	Good	NA	
	PD/1		NA	NA	NIA	NA	NA	NA	NA	NA	NA	
	DD42			NA			NA				NA	
	RR42	NOT LOCATED	INA Create Matel	Ditted	NA Ductod	NA Low	NA	NA			NA Foir	
MUNICIPAL	кк43	27		Pilled	Kusteu	(Bulkheaded)	None	NO	NA	Fall	Fdif	
MUNICIPAL	RR44	NOT LOCATED	NA	NA	NA	NA	NA	NA	NA	N/A	Excellent	
MUNICIPAL	RR45	30	Concrete	Pitted	Good	Low (Bulkheaded)	None	Yes	Clear	Good	Excellent	
MUNICIPAL	RR46	48	Concrete	Good	Pitted	Low (Bulkheaded)	None	Yes	Clear	Good	Good	
	RR47	60	Concrete	Good	Pitted	Low (Bulkheaded)	None	Yes	Clear	Good	Good	
MUNICIPAL	RR49	30	Concrete	Cracked	Crushed	Low (Bulkheaded)	None	No	NA	Poor	Poor	
MUNICIPAL	RR50	BULKHEADED	NA	NA	NA	NA	NA	NA	NA	N/A		
MUNICIPAL	RR51	18	Corrugated Metal	Rusted	Corroded	Moderate	None	Yes	Clear	Poor	Poor	
MUNICIPAL	RR53	54	Concrete	Good	Good	Moderate	None	Yes	Clear	Excellent	Excellent	
MUNICIPAL	RR55	NOT LOCATED	NA	NA	NA	NA	NA	NA	NA	NA	Excellent	
MUNICIPAL	PP56	10	Plastic	Good	Good	ΝΔ	None	Voc	Clear	Excellent	NA	
	PD57	10	Concrete	Good	Good		None	No	NIA	Excellent	Excellent	
	KK37	12	concrete	Good	Good	(Bulkheaded)	None	NO	NA	Excellent	excellent	
MUNICIPAL	RR58	18	Plastic	Good	Good	Low (Bulkheaded)	None	Yes	Clear	Excellent	Excellent	
MUNICIPAL	RR59	NOT LOCATED	NA	NA	NA	NA	NA	NA	NA	NA	Excellent	
MUNICIPAL	RR60	20	Concrete	Good	Good	Moderate	None	No	NA	Excellent	Excellent	
MUNICIPAL	RR60A	15	Concrete	Good	Good	Moderate	None	No	NA	Excellent	NA	
MUNICIPAL	RR61	60	Concrete	Good	Good	Low	None	Yes	Clear	Excellent	Excellent	

TABLE 5-7 OUTFALL ASSESSMENTS

TABLE 6-1

ALTERNATIVE STABILIZATION PRACTICES

INSTREAM PRACTICES
Vanes or J-Hook Vanes
Cross Vanes
STREAMBANK TREATMENT
Bank Shaping and Planting
Branch Packing
Brush Mattresses
Coconut Fiber Roll
Dormant Post Plantings
Vegetated Gabions
Joint Plantings
Live Cribwalls
Live Stakes
Live Fascines
Log, Rootwad, and Boulder Revetments
Riprap
Stone Toe Protection
Tree Revetments
Vegetated Geogrids

TABLE 6-2
STREAMBANK BUFFER SEED MIXTURE

Seed Mix	Pounds/ Acre
Andropogon scoparius	4
Anemone Canadensis	0.07
Aster lateriflorus	0.13
Bouteloua curtipendula	4.3
Calamagrostis Canadensis	0.13
Carex cristatella	1.33
Carex tribuloides	0.16
Echinacea pupurea	1.0
Eleocharis erythropoda	0.06
Elymus Canadensis	3.33
Elymus virginicus	1.5
Epilobium Coloratum	0.06
Eupatorium perfoliatum	0.07
Juncus dudleyi	0.01
Juncus torreyi	0.06
Leersia oryzoides	0.75
Liatris pycnostachya	0.18
Lobelia cardinalis	0.01
Leebelia silphitica	0.01
Physostegia virginiana	0.06
Poa palustris	1.67
Rudbeckia subtomentosa	0.06
Scirpus atrovirens	0.77
Scutellaria epilobifolia	0.13
Spartina pectinata	0.55
Sporobolus heterolepis	0.3
Sorghastrum nutans	3.67

BMP	Unit	Unit Cost
Vanes and J-Hook Vanes	each	\$1,000 - \$2,000
Cross Vanes	each	\$2,000 - \$6,000
Bank Shaping and Planting	square yard	\$40 - \$50
Brush Mattress	square yard	\$200 - \$500
Coconut Fiber Roll	square yard	\$10 - \$20
Coir Fabric	square yard	\$3 - \$7
Live Stakes	square yard	\$20 - \$60
Gabion (2 high)	foot	\$150 - \$200
Green Gabion (2 high)	foot	\$150 - \$250
Riprap	square foot	\$10 - \$15
Toe Protection	foot	\$25 - \$50
Joint Plantings	square foot	\$20 - \$30
Live Cribwall	foot	\$100 - \$150
Live Fascines	foot	\$20 - \$60
Rootwad	each	\$35 - \$50
Tree Revetment	foot	\$15 - \$30
Vegetated Geogrid	foot	\$50 - \$100

TABLE 7-1 COST FOR STREAM STABILIZATION PRACTICES

TABLE 7-2 ESTIMATED STREAMBANK STABILIZATION COSTS SITE JP1

Activity / Treatment	Units	Quantity	Unit Cost	Total Cost
Mobilization	LS	1	\$5,000	\$5,000
Regrading and Revegetating Banks	SY	300	\$50	\$15,000
Rock Toe Stabilization	Linear Feet	125	\$50	\$6,250
		Sub	total	\$26,000
		Engineeri	ng (15%)	\$4,000
		Permitti	ng (5%)	\$1,000
		Inspectio	on (10%)	\$3,000
		Continger	ncy (15 <mark>%</mark>)	\$4,000
		Estimated	Total Cost	\$38,000

TABLE 7-3ESTIMATED STREAMBANK STABILIZATION COSTSSITE JP2

Activity / Treatment	Units	Quantity	Unit Cost	Total Cost
Mobilization	LS	1	\$5,000	\$5,000
Regrading and Revegetating Banks	SY	4000	\$50	\$200,000
Rock Toe Stabilization	Linear Feet	1100	\$50	\$55,000
		Sub	total	\$260,000
		Engineeri	ng (15%)	\$39,000
		Permitti	ng (5%)	\$13,000
		Inspectio	on (10%)	\$26,000
		Continger	ncy (15 <mark>%</mark>)	\$39,000
		Estimated	Total Cost	\$377,000

TABLE 7-4
ESTIMATED STREAMBANK STABILIZATION COSTS
SITE JP3

Activity / Treatment	Units	Quantity	Unit Cost	Total Cost
Mobilization	LS	1	\$5,000	\$5,000
Regrading and Revegetating Banks	SY	200	\$50	\$10,000
Rock Toe Stabilization	Linear Feet	80	\$50	\$4,000
		Subt	total	\$19,000
		Engineeri	ng (15%)	\$3,000
		Permitti	ng (5%)	\$1,000
		Inspectio	on (10%)	\$2,000
		Continger	ncy (15%)	\$3,000
		Estimated	Total Cost	\$28,000

TABLE 7-5 ESTIMATED STREAMBANK STABILIZATION COSTS SITE CP1

Activity / Treatment	Units	Quantity	Unit Cost	Total Cost
Mobilization	LS	1	\$5,000	\$5,000
Regrading and Revegetating Banks	SY	600	\$50	\$30,000
Rock Toe Stabilization	Linear Feet	225	\$50	\$11,250
		Sub	total	\$46,000
		Engineeri	ng (15%)	\$7,000
		Permitti	ng (5%)	\$2,000
		Inspectio	on (10%)	\$5,000
		Continger	ncy (15%)	\$7,000
		Estimated	Total Cost	\$67,000

TABLE 7-6
ESTIMATED STREAMBANK STABILIZATION COSTS
SITE SS1

Activity / Treatment	Units	Quantity	Unit Cost	Total Cost
Mobilization	LS	1	\$5,000	\$5,000
Regrading and Revegetating Banks	SY	1700	\$50	\$85,000
Rock Toe Stabilization	Linear Feet	625	\$50	\$31,250
Subtotal				\$121,000
		Engineeri	ng (15%)	\$18,000
		Permitti	ng (5%)	\$6,000
		Inspectio	on (10%)	\$12,000
		Continger	ncy (15 <mark>%</mark>)	\$18,000
		Estimated	Total Cost	\$175,000

TABLE 7-7 ESTIMATED STREAMBANK STABILIZATION COSTS SITE SS2

Activity / Treatment	Units	Quantity	Unit Cost	Total Cost
Mobilization	LS	1	\$5,000	\$5,000
Rebuilding Retaining Wall	SF	600	\$50	\$30,000
		Sub	total	\$35,000
		Engineeri	ng (15%)	\$5,000
		Permitti	ng (5%)	\$2,000
		Inspectio	on (10%)	\$4,000
		Continger	ncy (15%)	\$5,000
		Estimated	Total Cost	\$51,000

TABLE 7-8 ESTIMATED STREAMBANK STABILIZATION COSTS SITE AM1

Activity / Treatment	Units	Quantity	Unit Cost	Total Cost
Mobilization	LS	1	\$5,000	\$5,000
Rebuilding Retaining Wall	SF	5500	\$50	\$275,000
		Sub	total	\$280,000
		Engineeri	ng (15%)	\$42,000
		Permitti	ng (5%)	\$14,000
		Inspectio	on (10%)	\$28,000
		Continger	ncy (15%)	\$42,000
		Estimated	Total Cost	\$406,000

TABLE 7-9ESTIMATED STREAMBANK STABILIZATION COSTSSITE CC1

Activity / Treatment	Units	Quantity	Unit Cost	Total Cost
Mobilization	LS	1	\$5,000	\$5,000
Regrading and Revegetating Banks	SY	1900	\$50	\$95,000
Rock Toe Stabilization	Linear Feet	500	\$50	\$25,000
		Sub	total	\$125,000
		Engineeri	ng (15%)	\$19,000
		Permitti	ng (5%)	\$6,000
		Inspectio	on (10%)	\$13,000
		Continger	ncy (15%)	\$19,000
		Estimated	Total Cost	\$182,000

TABLE 7-10
ESTIMATED STREAMBANK STABILIZATION COSTS
SITE MA1

Activity / Treatment	Units	Quantity	Unit Cost	Total Cost
Mobilization	LS	1	\$5,000	\$5,000
Regrading and Revegetating Banks	SY	5800	\$50	\$290,000
Rock Toe Stabilization	Linear Feet	1500	\$50	\$75,000
		Subt	total	\$370,000
		Engineeri	ng (15%)	\$56,000
		Permitti	ng (5%)	\$19,000
		Inspectio	on (10%)	\$37,000
		Continger	ncy (15%)	\$56,000
		Estimated	Total Cost	\$538,000

TABLE 7-11 ESTIMATED STREAMBANK STABILIZATION COSTS SITE WP1

Activity / Treatment	Units	Quantity	Unit Cost	Total Cost
Mobilization	LS	1	\$5,000	\$5,000
Regrading and Revegetating Banks	SY	4700	\$50	\$235,000
Rock Toe Stabilization	Linear Feet	1200	\$50	\$60,000
		Sub	total	\$300,000
		Engineeri	ng (15%)	\$45,000
		Permitti	ng (5%)	\$15,000
		Inspectio	on (10%)	\$30,000
		Continger	ncy (15%)	\$45,000
		Estimated	Total Cost	\$435,000

TABLE 7-12ESTIMATED STREAMBANK STABILIZATION COSTSSITE IL1

Activity / Treatment	Units	Quantity	Unit Cost	Total Cost
Mobilization	LS	1	\$5,000	\$5,000
Regrading and Revegetating Banks	SY	700	\$50	\$35,000
Rock Toe Stabilization	Linear Feet	250	\$50	\$12,500
		Sub	total	\$53,000
		Engineeri	ing (15%)	\$8,000
		Permitti	ng (5%)	\$3,000
		Inspectio	on (10%)	\$5,000
		Continger	ncy (15%)	\$8,000
		Estimated	Total Cost	\$77,000

		001					
Cost Itom				Outfall			
Cost item	P15	RR06	RR26	RR37E-1	RR37E-2	RR49	RR51
Pipe	\$1,000	\$2,000	\$500	\$3,000	\$10,000	\$1,000	\$500
Rip Rap	\$500	\$500	\$500	\$2,000	\$2,000	\$500	\$500
End Section	\$1,000	\$1,000	\$1,000	\$10,000	\$10,000	\$1,000	\$1,000
Subtotal	\$2,500	\$3,500	\$2,000	\$15,000	\$22,000	\$2,500	\$2,000
Mobilization, Inspection, Contingency	\$1,000	\$1,000	\$1,000	\$5,000	\$8,000	\$1,000	\$1,000
Total	\$3,500	\$4,500	\$3,000	\$20,000	\$30,000	\$3,500	\$3,000

TABLE 7-13 OUTFALL REPLACEMENT COST ESTIMATES

Application Funding Award Funding Eligible Applicants Funding Grant Contact **Grant Description Eligible Projects** Eligibility Criteria Deadline Source * Cycle Term DNR "River Protection Units of local 1. River organization Contact WDNR Regional River Planning Contact Grant Program" government development Office Environmental Grant WDNR 2. Information and Grants: \$10,000 Regional Nonprofit Specialist Office Protect rivers through conservation education max per grant and water quality, organizations 3. Assessments of Environmental fisheries habitat and Qualified river water quality, fish Grant 75% State share mix aquatic life and natural beauty management Specialist. organizations. enhancements. nonpoint source **River Management** evaluation. 4. Purchase of land Grants: \$50,000 max or easements 5. Development of per grant and 75% local ordinances 6. Restoration of in State Share max stream or shoreland habitat DNR Two years April 15, 2003 Implement urban runoff "Urban Nonpoint Local Stormwater • Funding Amount Every 1 performance standards (Wis. depends on the Source and Targeted governmental detention pond with a Second Admin Code NR151) units 2. Urban streambank biennial budget Runoff Management Year possible achieving water quality Grants" stabilization one year • 70% technical Note: standards protecting extension Land acquisition to assistance Depends groundwater. increase standard cost-share Promote urban runoff on permeable areas funding management for for infiltration. funds for 50% of the and existing, developing and redevelopment of number project cost of urban areas projects

TABLE 7-14 STREAMBANK FUNDING OPPORTUNITIES

www.dnr.wi.gov/aid/rivers.html

www.dnr.wi.gov/aid/urbannonpoint.html

TABLE 7-14 STREAMBANK FUNDING OPPORTUNITIES

Funding Source *	Grant Description	Eligible Applicants	Eligible Projects	Eligibility Criteria	Funding Award	Grant Cycle	Funding Term	Application Deadline	Contact
DNR	"Stewardship Program" To provide outdoor recreation, protect lands, sensitive to environmental degradation, conserve and restore wildlife habitat and protect water quality	Local units of government Nonprofit conservation	 Acquire property Urban Rivers: to restore an protect river corridors and river fronts in urban areas State Trails: Urban Green Space 	Depends if 501 © (3) status or a local government: Please see information on website listed under Contact information.	Funding varies by programs:	Contact local Community Service Specialist WDNR	Contact local Community Service Specialist WDNR	Contact local Community Service Specialist WDNR	<u>www.dnr.wi.go</u>
Fund for Lake Michigan (WE Energies)	Enhance the health of Lake Michigan and its shoreline and tributary river systems for the benefit of the people, plants and animals that depend upon the system for water, recreation and commerce.	Local units of government Nonprofit groups	Design and construction of projects the fulfill grant mission.	See information on website, listed under Contact information.	Varies	Varies	Varies	Varies	www.fundforla
EPA	Great Lakes Restoration Initiative (GLRI)	Local units of government Nonprofit groups	Multi-program initiative offering various grant programs over time. Visit website for latest grant program information.	See information on website, listed under Contact information.	Varies	Varies	Varies	Varies	www.epa.gov/

ov/topic/stewardship/grants/

akemichigan.org

//glnpo/glri/

Figures

















ea	end	Δ		
City Limits		Streambank Erosion Assessment Rating		
~		Moderate Erosion		
~				
>	E	Moderate Erosion/Buiknead		
4	SE	Moderately High Erosion		
A	S	Moderately High Erosion/Bulkhead		
Ь	SW	High Erosion		
<	W	High Erosion/Bulkhead		
\triangleright	NW			
tre	am	2013 Outfoll Define		
SS	essment	Outfall Rating		
•	Low	 Excellent 		
	Medium	Good		
	Medium to High	Fair		
	High	Poor		
		Not Pated		



ea	end			
	City Limits	Streambank Erosion Assessment Rating		
not	o Orientation	Low Erosion		
۵	Ν	Low Erosion/Bulkhead		
1	NE	Moderate Erosion		
⊳	E	Moderate Erosion/Bulkhead		
∢	SE	Moderately High Erosion		
A	S	Moderately High Erosion/Bulkhead		
Ь	SW	High Erosion		
<	W	■■■ High Erosion/Bulkhead		
\triangleright	NW			
tre	am	2013		
SS	essment	Outfall Rating		
	Low	 Excellent 		
	Medium	📀 Good		
	Medium to High	 Fair 		
	High	Poor		
		Not Rated		









Lege	ena	Stroombonk	Eracion
	City Limits	Assessment	Rating
Phot	o Orientation	Low Eros	sion
۵	Ν	Low Eros	sion/Bulkhead
4	NE	Moderate	e Erosion
۵	E	Moderate	e Erosion/Bulkhead
۷	SE	Moderate	ely High Erosion
A	S	Moderate	ely High Erosion/Bulkh
6	SW	High Ero	sion
4	W	High Ero	sion/Bulkhead
\triangleright	NW		
Stre	am	2013	5
Ass	essment	Outf	all Rating
	Low	\odot	Excellent
	Medium	$\overline{oldsymbol{\circ}}$	Good
	Medium to High	$\textcircled{\bullet}$	Fair
	High	\odot	Poor
		$\textcircled{\bullet}$	Not Rated

 $\sum_{\mathbf{N}}$ head 28 < JOHNSON PARK

100 50 Feet





Nov. 2013





				25	
ege	end	0	-		
	City Limits	Assessment	Erosion \widehat{N}	1	
ot	o Orientation	Low Erosion			
2	Ν	Low Ero	sion/Bulkhead	10	
7	NE	Moderate Erosion			
>	E	Moderate Erosion/Bulkhead			
١	SE	Moderately High Erosion			
7	S	Moderately High Erosion/Bulkhead			
5	SW	High Erosion			
3	W	High Erc	sion/Bulkhead		
>	NW				
tre SS(am essment	2013 Outf	3 all Rating		
•	Low	۲	Excellent		
	Medium	\overline{ullet}	Good		
	Medium to High	\overline{ullet}	Fair		
	High	\odot	Poor		
		\odot	Not Rated		

60263726

ГГ

RACINE ON THE LA

Nov. 2013

Figure 5-10 Root River Photo Location Areas Root River Assessment

City of Racine, Wisconsin





eg€	end	Ctreemberly		11
	City Limits	Assessment	t Rating	11
ot	o Orientation	Low Eros	sion	
2	Ν	Low Eros	sion/Bulkhead	
1	NE	Moderate	e Erosion	
>	E	Moderate	e Erosion/Bulkhead	0
1	SE	Moderate	ely High Erosion	
1	S	Moderate	ely High Erosion/Bulkhead	
5	SW	High Ero	sion	
3	W	High Ero	sion/Bulkhead	
~	NW			
tre	am essment	2013 Outf	all Rating	
	Low	•	Excellent	-
•	Medium	\overline{ullet}	Good	
•	Medium to High	\overline{ullet}	Fair	- La
•	High	\odot	Poor	
		$\textcircled{\bullet}$	Not Rated	-



1	A V	Westwood On	
ege	end City Limits	Streambank Erosion	S MIN
not	o Orientation	Low Erosion	
۵	Ν	Low Erosion/Bulkhead	
7	NE	Moderate Erosion	
>	E	Moderate Erosion/Bulkhead	
1	SE	Moderately High Erosion	No. of
7	S	Moderately High Erosion/Bulkhead	2
5	SW	High Erosion	
۲	W	High Erosion/Bulkhead	
\triangleright	NW		
tre sse	am essment	2013 Outfall Rating	
•	Low	Excellent	
	Medium	💿 Good	
	Medium to High	💿 Fair	1000
	High	• Poor	
		Not Rated	
	ligh St W		ALL THE

60263726

ΓΓΓ

RACINE ON THE LA

65 <

Nov. 2013

Root River Photo Location Areas

City of Racine, Wisconsin





egend City Limits		Streambank Erosion Assessment Rating		
A N		Low Erosion/Bulkhead		
1	NE	Moderate Erosion		
>	E	Moderate Erosion/Bulkhead		
1	SE	Moderately High Erosion		
1	S	Moderately High Erosion/Bulkhead		
5	SW	High Erosion		
3	W	High Erosion/Bulkhead		
~	NW			
tre sso	am essment	2013 Outfall Rating		
	Low	 Excellent 		
	Medium	📀 Good		
•	Medium to Hiah	• Fair		

S married

High

Not Rated

• Poor

Prospect St

60263726

ΓΓΓΙ

RACINE ON THE LAD

Nov. 2013

Root River Photo Location Areas

City of Racine, Wisconsin





-		A DESCRIPTION OF THE OWNER OWNER OF THE OWNER OWNER OF THE OWNER OW		100
ege not	end City Limits	Streambank Assessment Low Eros	Erosion And And And And And And And And And An	A CONTRACTOR
2	Ν	Low Eros	sion/Bulkhead	100
7	NE	Moderate Erosion		
>	E	Moderate Erosion/Bulkhead		
٦	SE	Moderately High Erosion		
7	S	Moderately High Erosion/Bulkhead		
\$	SW	High Ero	sion	
3	W	High Ero	sion/Bulkhead	1
~	NW			1
tre sso	am essment	2013 Outf	all Rating	
	Low	\odot	Excellent	
	Medium	\overline{ullet}	Good	
	Medium to High	\overline{ullet}	Fair	
•	High		Poor	





			the second se	CARGO INC.
ege	end	Stroombook	Fracion	$\overline{\mathbf{A}}$
	City Limits	Assessment	Rating	│
noto Orientation		Low Erosion		
2	Ν	Low Erosion/Bulkhead		
7	NE	NE Moderate Erosion		
>	E Moderate Erosion		e Erosion/Bulkhead	
۵	SE	Moderately High Erosion		
7	S	Moderately High Erosion/Bulkhead		
5	SW	High Erosion		
3	W	High Erosion/Bulkhead		
~	NW			
tream		2013		
ssessment		Outf	all Rating	
	Low	\odot	Excellent	İ
	Medium	\overline{ullet}	Good	1
	Medium to High	\overline{ullet}	Fair	
•	High	\odot	Poor	
		\odot	Not Rated	


ege	end City Limits o Orientation	Streambank Erosion Assessment Rating						
2	Ν	Low Erosion/Bulkhead	11					
7	NE	Moderate Erosion	-					
>	E	Moderate Erosion/Bulkhead	77					
1	SE	Moderately High Erosion						
1	S	Moderately High Erosion/Bulkhead						
5	SW	High Erosion						
3	W	High Erosion/Bulkhead	1					
2	NW							
tream ssessment		2013 Outfall Rating						
	Low	 Excellent 						
	Medium	📀 Good	-					
	Medium to High	• Fair	1					

High

Not Rated

• Poor

Glen S 144 60263726 Nov. 2013 Figure 5-17 Root River Photo Location Areas City of Racine, Wisconsin ГГ RACINE ON THE LA





1		Not little						
ege	end City Limits o Orientation	Streambank Assessment Low Eros	Erosion $\widehat{\bigwedge}_{N}$ Rating sion					
2	Ν	Low Eros	sion/Bulkhead					
7	NE	Moderate	Moderate Erosion					
>	E	Moderate Erosion/Bulkhead						
٦	SE	Moderately High Erosion						
7	S	Moderately High Erosion/Bulkhead						
5	SW	High Erosion						
3	W	■■■ High Erosion/Bulkhead						
~	NW							
tream ssessment		2013 Outfall Rating						
•	Low	\overline{ullet}	Excellent					
	Medium	\overline{ullet}	Good	-				
	Medium to High	\overline{ullet}	Fair					
•	High	(\bullet)	Poor	1-1				



18									
ege	end	\wedge							
City Limits		Streambank Erosion Assessment Rating							
hot	o Orientation	Low Erosion							
۵	Ν	Low Erosion/Bulkhead							
1	NE	Moderate Erosion							
	Е	Moderate Erosion/Bulkhead							
4	SE	Moderately High Erosion							
A	S	Moderately High Erosion/Bulkhead							
Ь	SW	High Erosion							
\triangleleft	W	High Erosion/Bulkhead							
\triangleright	NW								
trea	am	2013							
SSE	essment	Outfall Rating							
	Low	Excellent							
	Medium	💽 Good							
	Medium to High	💿 Fair							
	High	💿 Poor							
		 Not Rated 							
-	100								
		RR38							
		222 7 223							
	Ser in	A 221							
	A CONTRACT								
	SIS SPACE								
	60	1263726 Nov. 201							
		Figure 5-19							
		Root River Photo Location Areas							
		City of Racine, Wisconsin							



			2				
ege	City Limits	Streambank Erosion Assessment Rating					
	N	Low Erosion/Bulkhead					
1	NE	Moderate Erosion					
>	E	Moderate Erosion/Bulkhead	- 10				
1	SE	Moderately High Erosion	-				
1	S	Moderately High Erosion/Bulkhead					
5	SW	High Erosion					
3	W	High Erosion/Bulkhead					
~	NW						
tream ssessment		2013 Outfall Rating					
	Low	 Excellent 					
	Medium	💿 Good	R. C				
	Medium to High	💿 Fair	Service of				
•	High	• Poor					

Not Rated

60263726

ГГ

ACINE ON THE I

100

-Nov. 2013

11th St

Figure 5-20 Root River Photo Location Areas

MILL

City of Racine, Wisconsin







100								
ege	end City Limits o Orientation	Streambank Erosion Assessment Rating						
۵	Ν	Low Erosion/Bulkhead	1					
7	NE	Moderate Erosion						
>	E	Moderate Erosion/Bull	khead					
٩	SE	Moderately High Erosi	ion					
7	S	Moderately High Erosi	ion/Bulkhead					
5	SW	High Erosion						
4	W	High Erosion/Bulkhead						
~	NW		1					
tre sse	am essment	2013 Outfall Rating						
	Low	 Excellent 	t,					
	Medium	📀 Good						
	Medium to High	💿 Fair						
	High	Poor						
		Not Rated						
- 200	COLUMN STREET,		The second se					





Nov. 2013

60263726

Root River Photo Location Areas Root River Assessment

City of Racine, Wisconsin



Lege Phot	end City Limits o Orientation	Streambank Erosion Assessment Rating Low Erosion					
۵	Ν	Low Erosion/Bulkhead					
4	NE	Moderate Erosion					
⊳	E	Moderate Erosion/Bulkhead					
4	SE	Moderately High Erosion					
¥	S	Moderately High Erosion/Bull					
⊳	SW	High Erosion					
۷	W	High Erosion/Bulkhead					
	NW						

State St

RR57

HWN. 32

FTT

TT.

-

261

Hwy. 38

I DOM

100

TFee

50

10

2nd St

1

18.0

Dodge St

271

4

Dodge SI



Stream Assessment

Low Medium Medium to High High

2013 Outfall Rating

 \overline{N}

- \odot Excellent
- \odot Good
- \odot Fair
- \odot Poor
- \odot Not Rated

lkhead









its	Streambank Erosion Assessment Rating
Assessment	
d	Low Erosion/Bulkhead
Bulkhead	Moderate Erosion
osion	Moderate Erosion/Bulkhead
sion	Moderately High Erosion
Erosion	Moderately High Erosion/Bulkhead
to High Erosion	High Erosion
	High Erosion/Bulkhead



its Assessment	Streambank Erosion Assessment Rating	
d	Low Erosion/Bulkhead	
Bulkhead	Moderate Erosion	
osion	Moderate Erosion/Bulkhead	
sion	Moderately High Erosion	Core :
Erosion	Moderately High Erosion/Bulkhead	
to High Erosion	High Erosion	
	High Erosion/Bulkhead	VE



Appendix A

BEHI Worksheet and Rating Guide

	Bank Erodibility Hazard Rating Guide											
	Stream	-	Reach			_	Date	Э		Cre	w	
	Bank Height (ft):			Bank Height/	F	Root Depth/		Root	E	Bank Angle		Surface
	Bankfull Height (ft):			Bankfull Ht		Bank Height		Density %		(Degrees)	P	rotection%
		Value		1.0-1.1		1.0-0.9		100-80	T	0-20		100-80
	VERY LOW	Index		1.0-1.9		1.0-1.9	Γ	1.0-1.9		1.0-1.9	1	1.0-1.9
		Choice	V:	1:	V:	l:	V:	l:	V:	1:	V:	l:
		Value		1.11-1.19	L	0.89-0.5		79-55		21-60		79-55
_	LOW	Index		2.0-3.9		2.0-3.9		2.0-3.9		2.0-3.9	1	2.0-3.9
itia		Choice	V:	l:	V:	l:	V:	l:	V:	l:	V:	l:
ter		Value		1.2-1.5		0.49-0.3		54-30	T	61-80		54-30
Po	MODERATE	Index		4.0-5.9		4.0-5.9		4.0-5.9		4.0-5.9	[4.0-5.9
5		Choice	V:	l:	V:	l:	V:	l:	V:	l:	V:	l:
osi		Value		1.6-2.0		0.29-0.15		29-15	Τ	81-90		29-15
Ĕ	HIGH	Index		6.0-7.9		6.0-7.9		6.0-7.9		6.0-7.9		6.0-7.9
¥		Choice	V:	l:	V:	l:	V:	l:	V:	l:	V:	
Ba		Value	I	2.1-2.8		0.14-0.05		14-5.0		91-119		14-10
	VERY HIGH	Index		8.0-9.0		8.0-9.0		8.0-9.0	- 	8.0-9.0		8.0-9.0
		Choice	V:	l:	V:	l:	V:	l:	V:	l:	V:	l:
		Value		>2.8		<0.05		<5		>119		<10
	EXTREME	Index		10		10	[10		10		10
		Choice	V:	l:	V:	l:	V:	1:	V:	l:	V:	l:
	V = value, I = index					SUB-TOT	AL (Sum one inde	x from	each column)		

Bank Material Description:

Bank Materials

Bedrock (Bedrock banks have very low bank erosion potential)

Boulders (Banks composed of boulders have low bank erosion potential)

Cobble (Subtract 10 points. If sand/gravel matrix greater than 50% of bank material, then do not adjust)

Gravel (Add 5-10 points depending percentage of bank material that is composed of sand)

Sand (Add 10 points)

Silt Clay (+ 0: no adjustment)

BANK MATERIAL ADJUSTMENT

Stratification Comments:

Stratification

Add 5-10 points depending on position of unstable layers in relation to bankfull stage

STRATIFICATION ADJUSTMENT

VERY LOW	LOW	MODERATE	HIGH	VERY HIGH	EXTREME	
5-9.5	10-19.5	20-29.5	30-39.5	40-45	46-50	
Bank location descrip	otion (circle one)				GRAND TOTAL	
Straight Reach	Outside of Bend				BEHI RATING	

Appendix B

Pfankuch Rating Worksheet

PFANKUCH CHANNEL STABILITY EVALUATION

Deach Loca	catagory EXCELLENT		ervers							
Reach Luca			EXCELLENT		GOOD	FAIR		POOR		
r	1 1	Landform Slope	Bank Slope Gradient <30%	2	Bank slope gradient 30-40%	4	Bank slope gradient 40-60%.	6	Bank slope gradient 60% +	8
IIPPER		Mass Wasting	No evidence of past or future mass wasting	3	Infrequent, Mostly healed over, Low future potential	6	Frequent or large, causing sediment nearly year long.	9	Frequent or large causing sediment nearly year long	12
OFFER	1 ~								or imminent danger of same,	
BANKS	1 1	Debris Jam Potential	Essentially absent from immediate channel area.	2	Present, but mostly small twigs and limbs.	4	Moderate to heavy amounts, mostly larger sizes.	6	Moder, to heavy amounts, predom, larger sizes.	8
		Venetative Bank Protection	90%+ plant density. Vigor and variety suggest a	3	70-90% density. Fewer species or less vigor	6	<50-70% density. Lower vigor and fewer species	9	<50% density, fewer species and less vigor indicate	12
1	1		deep dense soil binding root mass.		suggest less dense or deep root mass.		form a shallow, discontinuous root mass.		poor, discontinuous and shallow root mass.	1
	5	Channel Cacacity	Ample for present plus some increases, Peak	1	Adequate, Bank overflows rare, W/D ratio 8-15.	2	Barely contains present peaks. Occasional overbank	3	Inadequate. Overbank flows common, W/D ratio >25	4
ł			Nows contained. W/D ratio <7				Roods. W/D ratio 15 to 25.			
IOWER	6	Baok Rock Content	65%+ with large angular boulders. 12"+ common	2	40-85%. Mostly small boulders to cobbles 6-12".	4	20-40% with most in the 3-6" diameter class,	6	<20% rock fragments of gravel sizes, 1-3" or less.	8
BANKS	7	Obstructions to Flow	Rocks and logs firmly imbedded. Flow pattern	2	Some present causing erosive cross currents and	4	Moder, frequent, unstable obstructions move with	6	Frequent obstructions cause erosion yeer-long.	8
	1		without cutting or deposition. Stable bed		minor poll filling. Obstructions newer and less firm.		high flows causing bank cutting and pool filling		Sediment traps full, channel migration occurring.	
	R	Cutting	Little or none, Infreq. raw banks less than 5	4	Some, intermittently at outcurves and constrictions.	-6	Significant, Cuts 12-24" high. Root mat overhangs	12	Almost continuous cuts, some over 24" high.	16
	ľ	Cathrig			Raw banks may be up to 12".		and sloughing evident.		Failure of overhangs frequent.	
	q	Deposition	Little or no enlargement of channel or pt, bars	4	Some new ber increase, mostly from coarse gravel,	8	Moder, deposition of new gravel and course sand	12	Extensive deposits of predominately fine particles.	16
	Ĭ	Dependent	-				on old and some new bars,		Accelerated bar development	·
	10	Rock Angularity	Sharp edges and corners. Plane surfaces rough.	1	Rounded corners and edges, surfaces smooth, flat.	2	Corners and edges well rounded in two dimensions.	3	Well rounded in all dimensions, surfaces smooth.	4
	11	Brightness	Surfaces dull, dark or stained, Gen, not bright.	1	Mostly dull, but may have <35% bright surfaces.	2	Modure dull and bright, is 35-85% medure range.	3	Predom, bright, 85%+ exposed or scoured surfaces.	4
BOTTOM	1 12	Consolidation of Particles	Assorted sizes bandy pecked or overlapping	2	Moderately packed with some overlapping.	4	Mostly loose assortment with no apparent overlap,	6	No packing evident, Loose assortment easily moved.	8
	1 13	Bottom Size Distribution	No size change evident, Stable mater, 80-100%,	4	Distribution shift light. Stable material 50-80%.	8	Moder, change in sizes, Stable materials 20-50%,	12	Marked distribution change, Stable materials 0-20%.	16
	14	Scouring and Denosition	<5% of bottom affected by scour or deposition.	6	5-30% affected. Scour at constrictions and where	12	30-50% affected. Deposits & scour at obstructions,	18	More than 50% of the bottom in a state of flux or	24
l					grades steepen. Some deposition in pools.		constrictions, and bends. Some filling of pools.		change nearly year-long.	
1	15	Acuatic Vegetation	Abundant Growth moss-like, dark green,	1	Common, Algal forms in low velocity and pool	2	Present but spoty, mostly in beckweter. Seesonal	3	Perennial types scarpe or absent. Yellow-green,	4
			perennial, in swift water too.		areas. Moss here too.		algal growth makes rocks slick		short term bloom may be present.	
	í	<u> </u>								
			lotais		4 -		•			
			L	•	4 .					

Stream Width x avo depth x mean velocity=Q	Sediment Supply	Stream Bed Stability	:
	Extreme	Aggrading	<u>م</u>
Gauge Ht	High	Stable	
Width Bf	Moderate		_
	Low	TOTAL SCORE for Reach E	+ G
Drainage Area			
	Remarks	• • • • • • • • • • • • • • • • • • • •	******************
Sinuosity			

Stream Type	A1 -	A2	A3	A4	A5	A6	B1	B2 ·	B3	B4	B5	B 6	C1	C2	ငဒ	C4	ය
good	38-43	38-43	54-90	60-95	60-95	50-80	38-45	38-45	40-60	40-64	48-68	40-60	38-50	38-50	60-85	^{.70-90}	70-90
Fair	44-47	44-47	91-129	96-132	96-142	81-110	46-58	46-58	61-78	65-84	69-88	61-78	51-61	51-61	86-105	91-110	91-110
Poor	48+	48+	130+	133+	143+	111+	59+	59+	79+	85+	89+	79+	62+	62+	106+	111+	111+
Stream Type	DA3	DA4	DA5	DA6	E3	E4	£5	E6	F1	F2	F3	F4	F5	F6	G1	G2	G3
GOOD	40-63	40-63	40-63	40-63	40-63	50-75	50-75	40-63	60-85	60-85	85-110	85-110	90-115	80-95	40-60	40-60	85-107
FAIR	64-86	64-86	64-86	64-86	64-86	76-96	76-96	64-86	86-105	86-105	111-125	111-125	116-130	96-110	61-78	61-78	108-120
POOR	87+	87+	87+	87+	87+	97+	97+	87+	106+	106+	126+	126+	131+	111+	79+	79+	121+

Width/Depth Ratio Condition Stream Normal Туре High..... Very High..... Pfankuch+ F.....= Rating Reach from ****** Condition table D5 D6 D3 D4 C6 67-98 85-107 85-107 85-107 60-85 99-125 108-132 108-132 108-132 86-105 133+ 133+ 126+ 106+ 133+ G5 G6 G4 85-107 85-107 90-112 108-120 113-125 108-120 126+ 121+ 121+

Appendix C

Photo Logs



Photo 1





Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14

7



Photo 15



Photo 16



Photo 17





Photo 19





Photo 21





Photo 23





Photo 25





Photo 27





Photo 29





Photo 31





Photo 33




Photo 35



Photo 36



Photo 37





Photo 39





Photo 41



Photo 42



Photo 43





Photo 45





Photo 47





Photo 49





Photo 51





Photo 53



December 2013



Photo 55



December 2013



Photo 57





Photo 59





Photo 61





Photo 63





Photo 65





Photo 67





Photo 69



Photo 70



Photo 71



Photo 72



Photo 73



Photo 74



Photo 75



Photo 76

38



Photo 77





Photo 79





Photo 81





Photo 83





Photo 85



Photo 86



Photo 87





Photo 89





Photo 91



Photo 92



Photo 93





Photo 95





Photo 97





Photo 99





Photo 101





Photo 103





Photo 105



53


Photo 107





Photo 109





Photo 111





Photo 113





Photo 115





Photo 117





Photo 119





Photo 121





Photo 123





Photo 125





Photo 127





Photo 129





Photo 131





Photo 133





Photo 135





Photo 137



Photo 138



Photo 139





Photo 141





Photo 143





Photo 145





Photo 147





Photo 149





Photo 151





Photo 153





Photo 155





Photo 157



December 2013



Photo 159





Photo 161





Photo 163





Photo 165





Photo 167





Photo 169





Photo 171



Photo 172



Photo 173



Photo 174



Photo 175



December 2013



Photo 177




Photo 179





Photo 181





Photo 183





Photo 185





Photo 187



Photo 188



Photo 189



 $\label{eq:linear} L: work \end{tabular} big the linear term of t$



Photo 191





Photo 193





Photo 195





Photo 197





Photo 199



Photo 200



Photo 201





Photo 203



Photo 204



Photo 205





Photo 207





Photo 209





Photo 211



Photo 212



Photo 213



107



Photo 215



Photo 216



Photo 217





Photo 219





Photo 221





Photo 223



Photo 224



Photo 225





Photo 227



114



Photo 229



115



Photo 231





Photo 233





Photo 235





Photo 237



Photo 238



Photo 239





Photo 241





Photo 243





Photo 245





Photo 247





Photo 249




Photo 251





Photo 253



127



Photo 255





Photo 257





Photo 259





Photo 261





Photo 263





Photo 265





Photo 267





Photo 269







Photo 271